



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 7/4/2020

Vehicle: SMN3363E

Make / Model: HONDA SHUTTLE

Chassis: GP7-2001839

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR TAILGATE / DD	1	\$ 1,493.00	\$ 1,493.00
2	REAR TAILGATE LOCK / DT	1	\$ 167.10	\$ 167.10
3	REAR TAILGATE LOCK CATCH X NN	1	\$ 47.50	\$ 47.50
4	REAR TAILGATE INNER TRIME BOARD / CRV	1	\$ 426.00	\$ 426.00
5	REAR TAILGATE OUTER CHROME MOULDING / DR	1	\$ 483.10	\$ 483.10
6	REAR TAILGATE INNER HANDLER X NN	1	\$ 45.00	\$ 45.00
7	REAR BUMPER / DD	1	\$ 1,356.40	\$ 1,356.40
8	REAR BUMPER SPONGE / CRV	2	\$ 96.50	\$ 193.00
9	REAR BUMPER SIDE RETAINER LH / DR	1	\$ 46.50	\$ 46.50
10	REAR BUMPER SIDE RETAINER RH / DR	1	\$ 46.50	\$ 46.50
11	REAR BUMPER REFLECTOR LH X NN	1	\$ 75.00	\$ 75.00
12	REAR BUMPER REFLECTOR RH X NN	1	\$ 75.00	\$ 75.00
13	REAR BUMPER REFLECTOR COVER LH / CRV	1	\$ 85.00	\$ 85.00
14	REAR BUMPER REFLECTOR COVER RH / CRV	1	\$ 85.00	\$ 85.00
15	REAR WEATHER STRIPE / CRV	1	\$ 188.60	\$ 188.60
16	REAR TAILGATE EMBLEM SHUTTLE / MK	1	\$ 85.00	\$ 85.00
17	REAR TAILGATE EMBLEM HYBRIDE / MK	1	\$ 90.10	\$ 90.10
18	REAR TAILGATE EMBLEM LOGO / MK	1	\$ 68.00	\$ 68.00
19	REAR END PANEL / DD	1	\$ 760.80	\$ 760.80
20	REAR END PANEL TOP GARNISH / CRV	1	\$ 185.50	\$ 185.50
				\$ 6,002.10
Less 20%				\$ 1,200.42
Total				\$ 4,801.68
S/Nett items:				
1	REAR REVERSE SENSOR / DM	1 SET	\$ 250.00	\$ 250.00
2	REAR BUMPER CLIP / MK	1 SET	\$ 80.00	\$ 80.00
3	REAR END PANEL GARNISH CLIP / MK	1 SET	\$ 30.00	\$ 30.00
4	FLOOR PANEL SEALANT X NN	1	\$ 50.00	\$ 50.00
5	REAR WINDSCREEN GLASS SEALANT / MK	1	\$ 60.00	\$ 60.00
6	END PANEL SEALANT / MK	1	\$ 50.00	\$ 50.00
				\$ 520.00

Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00
2	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$ 150.00
3	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00
4	REMOVE AND REFIX REAR WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00
5	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00
6	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00
7	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00
				\$ 2,730.00
			Parts Replacement Amount	\$ 5,321.68
			Total Amount for Labour	\$ 2,730.00
			Total Amount	\$ 8,051.68

30
30
30
120
x
600
800

Steve (LKK) ML M
7/4/20, 12.2021
S J
L/S
M J L M

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 7/4/2020

Vehicle: SMN3363E

Make / Model: HONDA SHUTTLE

Chassis: GP7-2001839

Supplementary

No.	Description	Unit	Unit Price	Amount
	Parts Replacement:			
1	REAR BUMPER REFLECTOR INNER SPONGE LH X N	N 1	\$ 86.50	\$ 86.50
2	REAR BUMPER REFLECTOR INNER SPONGE RH X N	N 1	\$ 86.50	\$ 86.50
3	REAR BOOT GARNISH BOX ✓ CR4	1	\$ 358.60	\$ 358.60
				\$ 531.60
			Less 20%	\$ 106.32
			Total	\$ 425.28