

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

NOT Authorized
L/Ring & ?
Preserving After Paint
16 days

Date : 02/04/2020

QUOTATION -THIRD PARTY CLAIM

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Attn: Motor Claim Department . Officer In Charge

Claim : Third Party Claim
Veh. No : SLT 2124 R
Model : TOYOTA WISH
Insured Ins: NTUC INCOME

Accident on : 02/04/2020

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : GBE 4302 C		
1	TAILGATE <i>Bz</i>	\$ 1,480.00	✓
1	TAILGATE LOCK	\$ <i>Tn</i> 385.00	✓
1	TAILGATE LOCK SENSOR	\$ 335.00	?
1	TAILGATE TOP SPOILER	\$ 1,128.00	?
1	TAILGATE W/SCREEN <i>Shorten</i>	\$ 1,848.00	✓
1	TAILGATE W/SCREEN MOULDING <i>nu</i>	\$ 280.00	✓
2	TAILGATE W/SCREEN INNER SIDE GARNISHS <i>Di'i</i>	\$ <i>Bz</i> 776.00	✓
1	TAILGATE THIRD BRAKE LAMP	\$ 650.00	?
1	TAILGATE OUTER CHROME MOULDING <i>CM</i>	\$ 580.00	✓
1	TAILGATE OUTER CHROME INNER SWITCH	\$ 332.00	?
2	TAILGATE REFLECTORS <i>CM</i>	\$ 960.00	✓
1	TAILGATE TRIM BOARD <i>Bz</i>	\$ 540.60	✓
8	TAILGATE TRIM BOARD CLIPS <i>nu</i>	\$ 32.00	✓
1	TAILGATE LOWER COVER	\$ 185.00	?
1	TAILGATE CENTER LOGO <i>nu</i>	\$ 65.00	✓
1	TAILGATE VAVE MATIC EMBLEM <i>nu</i>	\$ 68.00	✓
2	TAILGATE HINGES <i>R</i>	\$ 448.00	X
2	TAILGATE ABSORBERS	\$ 778.00	?
1	TAILGATE WIPER MOTOR <i>Tn</i>	\$ 685.00	✓
1	TAILGATE WIPER ARM <i>nu</i>	\$ 323.00	✓
1	REAR FENDER LH <i>R</i>	\$ 840.00	X
1	REAR FENDER RH <i>Bz</i>	\$ 840.00	✓
2	REAR FENDER UNDERSHIELDS <i>Bz</i>	\$ 560.00	X
20	REAR FENDER UNDERSHIELD CLIPS <i>nu</i>	\$ <i>nu</i> 70.00	X
2	REAR FENDER INNER SIDE TRIM BOARDS <i>ols Bz</i>	\$ 1,250.00	n/s ?
2	REAR FENDER INNER SIDE TRIM TOPS <i>ols Di'i</i>	\$ 780.00	✓
1	REAR FENDER QUARTER GLASS RH <i>Shorten</i>	\$ 588.45	✓
1	REAR FENDER QUARTER GLASS SIDE GARNISH <i>Di'i</i>	\$ 288.00	✓
1	REAR FENDER AIR DUCT RH <i>nu</i>	\$ 212.00	✓
2	TAILLAMPS <i>n/s ?</i>	\$ <i>ols Bz</i> 1,380.00	✓
2	TAILLAMP PANELS <i>ols Bz</i>	\$ 448.00	✓
2	TAILLAMP SIDE CLIPS <i>ols nu</i>	\$ 40.00	✓
2	TAILLAMP SOCKETS ASSY	\$ 596.00	?
2	TAILLAMP LOWER RETAINERS <i>ols Di'i</i>	\$ 280.00	✓
1	REAR DOOR RH	REPAIR	
1	REAR DOOR LOCK RH	\$ 480.00	?
1	END PANEL INNER <i>Bz</i>	\$ 480.00	✓
1	END PANEL OUTER <i>Bz</i>	\$ 552.00	✓
1	END PANEL TOP GARNISH	\$ 435.00	?

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

5	END PANEL TOP CLIPS	<i>me</i>	\$	25.00	✓
1	END PANEL TOP LATCH		\$	78.00	?
1	END PANEL LATCH LOCK SWITCHES		\$	288.00	?
1	FLOOR PANEL		\$	980.00	?
1	FLOOR PANEL TOP BOARD		\$	689.00	?
2	FLOOR PANEL SIDE BOARDS		\$	880.00	?
1	FLOOR PANEL TOP INSULATOR		\$	440.00	?
1	REAR SEAT RH		\$	1,685.00	?
1	REAR SEAT LH		\$	2,200.00	?
2	REAR SEAT BRACKETS		\$	480.00	?
2	REAR SEAT CABLES	<i>me</i>	\$	680.00	X
1	REAR SEAT LOWER PANEL			REPAIR	
1	REAR SEAT LOWER GARNISH		\$	552.00	?
1	ROOF UPHOLSTERY	<i>cm</i>	\$	1,985.00	✓
1	ROOF PANEL			REPAIR	
1	SPARE TYRE CENTER SCREW		\$	285.00	?
2	REAR CHASSIS			REPAIR	
1	REAR EXHAUST		\$	685.00	?
1	REAR EXHAUST HEAT SHIELD		\$	<i>me</i> 385.00	X
1	REAR EXHAUST MOUNTING		\$	285.00	?
1	REAR BUMPER		\$	<i>me</i> 840.00	✓
2	REAR BUMPER SIDE SCREWS		\$	40.00	?
10	REAR BUMPER CLIPS		\$	<i>me</i> 35.00	✓
2	REAR BUMPER BRACKETS		\$	<i>me</i> 260.00	✓
2	REAR BUMPER SIDE RETAINERS	<i>cls dir</i>	\$	280.00	LT
2	REAR BUMPER REFLECTORS	<i>cls dir</i>	\$	580.00	LT
2	REAR BUMPER SENSORS	<i>me</i>	\$	480.00	2005n
2	REAR BUMPER SENSOR CABLES		\$	385.00	?
			\$	37,500.05	
		Less 25%	\$	9,375.01	
			\$	28,125.04	
	S/NETT				
2TUBE	REAR W/SCREEN SEALANT	<i>me</i>	\$	140.00	405n
1 TUBE	REAR RH QUARTER GLASS SEALANT	<i>me</i>	\$	70.00	305n
1	REAR W/SCREEN SOLAR FLIM	<i>me</i>	\$	480.00	1201n
1	WIPER BLADE		\$	220.00	?
1SET	REVERSE CAMERA ASSY		\$	500.00	?
1SET	CAR DASHCAM 2 CHANNEL		\$	<i>me</i> 800.00	✓
1	SPARE TYRE		\$	<i>me</i> 480.00	X
1	SPARE TYRE JACK		\$	280.00	?
1	REAR TYRE LH		\$	<i>me</i> 400.00	X
	S/NETT PARTS :		\$	3,370.00	
	TOTAL PARTS :		\$	31,495.04	

AE AUTO PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-01
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

QTY	LABOUR	AMOUNT	SURVEYOR
	Balance b/f	\$ 31,495.04	
	Towing Charges	REFER INV	
	Labour charges to do cutting , welding, replace repair, align adjust, remove refix rear accident affected area	\$ 2,200.00	1800h
	To replace and check on rear lamp wiring systems	\$ 200.00	301
	To replace dashcam, replace sensor and cables, replace reverse camera, replace solar flim (accessories)	\$ 300.00	1201
	Remove refix, replace side trims, garnish, trim board, upholstery car seat, seat belt etc for rear	\$ 500.00	1201
	To do anti rust	\$ 120.00	✓
	To do selant, seal gap, waterproofing , on cut welding affected area	\$ 250.00	801
	Transfer tailgate parts to another tailgate	\$ 100.00	601
	Replace rear w/screen	\$ 140.00	1201
	To do rear chassis body alignment	\$ 350.00	7
	To replace rear exhaust	\$ 180.00	601
	To do spray painting on accident affected area, inner outer .	\$ 2,000.00	1800h
	TOTAL LABOUR :	\$ 6,340.00	
	Total Parts & Labour :	\$ 37,835.04	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: