

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block
MND Complex
Singapore 069110

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jaime Tay

Date: 04 Jun 2020

Preliminary Advice

Insured Vehicle No	: SKZ4112S		
TP Vehicle No	: SLK3684G	Accident Date	: 01/04/2020
Make	: FORD FIESTA TITANIUM	Assignment Date	: 03/04/2020
Date of Inspection	: 06/04/2020	Est. Duration of Repair	: 12.00
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) BLK 1008, #01-04/06/08/94, BUKIT MERAH LANE 3 SINGAPORE 159722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s & front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,322.64
Revised Amount	:S\$	14,504.00
Check Items (Estimated)	:S\$	499.00
Total	:S\$	15,003.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a without "prejudice" basis.