

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Apr 2020)
 Parts: 144 FORD FIESTA TITANIUM 998cc (A) (Catalogue Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SLK3684G)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT GRILLE ASSY <i>crn</i>	20.00	0.00	715 - *890.00 FL
2	1		*FRONT BUMPER EMBLEM <i>ne</i>	20.00	0.00	62 - *160.00 FL
3	1		*REAR BUMPER <i>horn</i>	20.00	0.00	1502 - *1,635.00 FL
4	1		*REAR BUMPER LOWER <i>horn</i>	20.00	0.00	463 - *895.00 FL
5	1		*REAR BUMPER REFLECTOR LAMP LH <i>bro</i>	20.00	0.00	198 - *260.00 FL
6	1		*REAR BUMPER PARKING SENSOR LH <i>mis</i> <i>clip 7 @ 265</i>	20.00	0.00	265 - *760.00 FL
7	1		*REAR BUMPER SIDE RETAINER LH <i>crn</i>	20.00	0.00	116 - *240.00 FL
8	1		*REAR BUMPER REINFORCEMENT <i>bt</i>	20.00	0.00	1 - *799.00 FL
9	10		*REAR BUMPER CLIPS <i>ne</i>	20.00	0.00	1 - *50.00 FL
10	1		*REAR FENDER LH <i>bu</i>	20.00	0.00	1300 - *1,845.00 FL
11	1		*REAR FENDER INNER TRIM LH <i>xsvl</i>	20.00	0.00	*998.00 FL X
12	1		*REAR FENDER AIR VENT LH <i>crn</i>	20.00	0.00	*210.00 FL
13	1		*TAIL LAMP LH <i>xsvl</i>	20.00	0.00	*850.00 FL X
14	1		*TAILGATE <i>bt</i>	20.00	0.00	1 - *1,945.00 FL
15	1		*TAILGATE (TITANIUM) EMBLEM <i>ne</i>	20.00	0.00	45 - *160.00 FL
16	1		*TAILGATE (ECOBOOST) EMBLEM <i>ne</i>	20.00	0.00	65 - *160.00 FL
17	1		*TAILGATE (FIESTA) EMBLEM <i>ne</i>	20.00	0.00	83 - *150.00 FL
18	1		*TAILGATE GLASS MOULDING <i>ne</i>	20.00	0.00	165 - *290.00 FL
19	1		*TAILGATE RUBBER <i>ne</i>	20.00	0.00	253 - *395.00 FL
20	1		*END PANEL GARNISH <i>bt</i> <i>xsvl</i>	20.00	0.00	*499.00 FL X
21	1		*END PANEL ASSY <i>bt</i>	20.00	0.00	853 - *1,340.00 FL
22	1		*REAR WINDSCREEN SEALANT <i>ne</i>	0	0.00	51446 - *40.00 FS
23	1		*FRONT NUMBER PLATE <i>xsvl</i>	0	0.00	*50.00 FS X

F=Franchise part S=SpcNett L=ListItemDisc

Sub Total (\$\$) 14,621.00
 - List Item Discount on L Items (\$\$) 2,906.20
 Total Parts (\$\$) 11,714.80

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO INSPECT REAR LIGHTING WATER & LEAKAGE TEST	New	40.00 XAN
2	TO REMOVE & INSTALL TAILGATE GLASS	New	120.00
3	TO REMOVE & TRANSFER ITEMS TO NEW TAILGATE	New	100.00 60
4	TO REMOVE & INSTALL FUEL TANK	New	80.00
5	TO REMOVE & INSTALL REAR COMPARTMENT, GARNISHES, CARPET & ETC IN ORDER TO CUT OFF LH REAR FENDER, END PANEL	New	300.00 100
6	TO CUT OFF END PANEL, LH REAR FENDER, STRAIGHTEN AFFECTED AREAS AND RENEW DAMAGED PARTS	New	1200 1000 1000
7	TO APPLY BODY JOINT SEALANT ON CUTTING AREAS	New	40.00
8	TO APPLY RUST PROOF ON AFFECTED AREAS	New	60.00
9	TO SPRAY PAINT ON REPLACED, REPAIRED AREAS	New	1,200.00 1000
Gross Labour Cost (\$\$)			3,540.00 2660

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rasul
Hp 900 100 68

12 days

4s

06/04/2022

@1450

Rey after repair

7264.00

40.00

2660.00

9964.00

20%

7971.20

4s-7950

12 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sent: Wed 27/5/2020 10:33 AM

To: Rasul (LKKAUTO)

Confirm thanks!

Best Regards

Alan Chng

Claims Estimator

Mova Automotive Pte Ltd

H/P 9686 9276

Office No:6262 3377

Fax No:6264 3151

I

-----Original Message-----

From: Rasul (LKKAUTO) [<mailto:Rasul@lkkauto.com>]

Sent: Tuesday, 26 May 2020 11:51 AM

To: Alan Chng

Subject: RE: finalization for veh no:SLK3684G

Hi alan,

Refer to attachment

Finalised amount is \$ 7950 / 12 days of lump sum repair



Alan Chng

All folders are up to date.



Connected to Microsoft