

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

**TAX INVOICE**

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. NA2002892
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE
SINGAPORE 189556

INV Date 18/05/2020
Reference NS/INC20004963/Fyf3n2
Code INC4

**PROFESSIONAL SERVICE FEE**

Vehicle No. SHA 3314A
Insured Veh. GW 634S
Claim No. MT/1090746-003
Policy No. 5075274775-04
Accident Date 03/04/2020
Inspection Date 03/04/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'National Assessment Centre Services'**

National Assessment Centre Services***HYN***




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20004963/Fyf3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 18-05-2020	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GW 634S	Veh. Inspected	SHA 3314A	
Policy No.	5075274775-04	Coverage (\$)	0.00	
Claim No.	MT/1090746-003	Excess (\$)	0.00	
Assign From		Assign Date	03/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	JTDKB3FU303091178	Colour	BLUE	
Odometer	17251	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	DUNLOP	9 mm	
L/H Front Tyre	195/65 R15	DUNLOP	9 mm	
R/H Rear Tyre	195/65 R15	DUNLOP	9 mm	
L/H Rear Tyre	195/65 R15	DUNLOP	9 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	03/04/2020	Inspection Date	03/04/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 3314A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	CRACKED / DEFORMED	458.60	458.60
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	318.80	-
1	REAR BUMPER UNDERCOVER	SCRATCHED	552.60	552.60
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR BUMPER REFLECTOR-LH	NOT NECESSARY	55.00	-
1	REAR BUMPER UNDER SIDE COVER-LH	NOT NECESSARY	232.00	-
1	SEAL,REAR BUMPER SIDE-LH	NOT NECESSARY	148.40	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,126.60	-
1	TAILGATE TOYOTA EMBLEM	NECESSARY	52.90	52.90
1	TAILGATE PRIUS EMBLEM	NECESSARY	60.80	60.80
1	TAILGATE HYBRID EMBLEM	NECESSARY	52.40	52.40
1	TAILGATE GARNISH	TO REPAIR SEE LABOUR	889.70	-
1	TAILGATE WINDSCREEN	NOT NECESSARY	1,778.30	-
1	TAILGATE LOWER GLASS	NOT NECESSARY	1,569.70	-
	LESS 25% DISCOUNT		-1,829.45	-299.83
			5,488.35	899.47
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
1	REAR BUMPER RUBBER MAT (SN)	NOT NECESSARY	50.00	-
1	TAILGATE APP STICKER (SN)	NECESSARY	40.00	40.00
1	TAILGATE COMFORT & TEL STICKERS (SN)	NECESSARY	60.00	60.00
			285.70	100.00
<u>LABOUR</u>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TAILGATE AND TAILGATE GARNISH.		1,000.00	640.00
	SPRAY PAINTING CHARGE.		500.00	400.00
	REMOVE/REFIX REVERSE SENSOR.		80.00	60.00
	WIRING CHARGE.		80.00	50.00

Report Ref No. NS/INC20004963/Fyf3n2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
			1,810.00	1,150.00
GRAND TOTAL			7,584.05	2,149.47
RECOMMENDED COST OF REPAIRS (CONFIRMED)				2,149.47

Report Ref No. NS/INC20004963/Fyf3n2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.