

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Keny Ong Thiam Beng	Date:	20 Apr 2020

Preliminary Advice

Insured Vehicle No	:	SLK4430R		
TP Vehicle No	:	SJU7126X	Accident Date	: 03/04/2020
Make	:	TOYOTA VIOS	Assignment Date	: 07/04/2020
Date of Inspection	:	06/04/2020	Est. Duration of Repair	: 5.00
Inspection At	:	ASIA MOTORSPORTS SOLUTION PTE LTD (HQ) 37A EVERITT SINGAPORE 428586		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 11,404.95
Revised Amount	:	S\$ 4,439.55
Check Items (Estimated)	:	S\$ 0.00
Total	:	S\$ 4,439.55
Lump Sum Repair		
	:	S\$ 3,550.00

Total Loss Consideration

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.