



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2102649

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 15/04/2021
Reference CC4/FCI20004979/Aes3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SFS 9754C
Insured Veh. SHC 3379C
Claim No. D20001791MFSH
Policy No. D-20094922MFSH
Accident Date 02/04/2020
Inspection Date 04/08/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20004979/Aes3q2	
			Date: 15/04/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHC 3379C	Veh. Inspected	SFS 9754C
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00
	Claim No.	D20001791MFSH	Excess (\$)	0.00
	Assign From	CHRIS	Assign Date	04/08/2020
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	JM6BM42A8F0167095	Colour	SILVER
	Odometer	27250 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/50 R16	TOYO	6 mm
	L/H Front Tyre	205/50 R16	TOYO	6 mm
	R/H Rear Tyre	205/50 R16	TOYO	6 mm
	L/H Rear Tyre	205/50 R16	TOYO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	02/04/2020	Inspection Date	04/08/2020
	Survey held at	PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFS 9754C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,083.30	1,083.30
10	FRONT BUMPER CLIPS @\$4.80	NECESSARY	48.00	48.00
1	FRONT BUMPER SIDE HOLDER -LH	NECESSARY	19.70	19.70
1	FRONT BUMPER SIDE HOLDER -RH	NOT NECESSARY	19.70	-
1	FRONT BUMPER FOG LAMP -LH	NOT NECESSARY	369.00	-
1	FRONT BUMPER FOGLAMP COVER -LH	CUT	48.80	48.80
1	FRONT FENDER -LH	DENTED	350.60	350.60
1	FRONT FENDER COWLING -LH	TORN	101.90	101.90
1	FRONT FENDER COWLING CLIPS -LH	NECESSARY	48.00	48.00
1	HEADLAMP ASSY -LH	CUT	2,357.30	2,357.30
1	HEADLAMP LOWER RETAINER -LH	NOT NECESSARY	15.90	-
	LESS 20% DISCOUNT		-892.44	-811.52
			3,569.76	3,246.08
	<u>LABOUR</u>			
	TO KNOCK OUT DENTS ,REMOVE ,REPLACE ACCIDENT PARTS.		600.00	400.00
	TO RESPRAY PAINT ON ACCIDENT PORTIONS.		600.00	400.00
	TO CHECK WIRING .		50.00	30.00
	TO TUFF -KOTE.	NOT NECESSARY	30.00	-
			1,280.00	830.00
	GRAND TOTAL		4,849.76	4,076.08
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,250.00

Report Ref No. CC4/FCI20004979/Aes3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFS 9754C

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

