

ASS. REC. BY: Toughlin

REF:


716

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$32K.
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G6E2560L Yr Regn: 2015, Oct
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Nissan NV200 c.c 1461
Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 139073 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: VSKYBAM20Z 0108471
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 175/70 R14
R: 7 -
BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front: C mm Rear: C mm
R/Bal. C mm L/Bal. C mm
D.O.A. _____ D.O.I. 7/1/2024
Survey held at EM-1 Auto.
Des. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Singh, Arjun
#5

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Rep. Form: _____

Lump Sum / L.B.I. (\$ _____)

TOTAL

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : GBE 2560L
Vehicle Model : NISSAN NV200
Accident Date : 05.04.2020
Original Reg Date : 14.10.2015

Date : 06.04.2020
Chassis : VSKYBAM20Z0108471
TP Ins. **AIG**

ESTIMATE

1	1 pc	Tailgate LH		1,404.90	Nbt
2	1 pc	Tailgate Windscreen Inner Seal LH		60.00	Nrei
3	1 pc	Tailgate Badge		78.20	Nrei
4	1 pc	Tailgate Emblem NV200		125.10	Nrei
5	1 pc	Tailgate Upper Lock LH		153.50	Nx
6	1 pc	Tailgate Upper Lock Catch LH		46.20	Nx
7	1 pc	Tailgate Inner Bottom Lock LH		153.50	N?
8	1 pc	Tailgate Inner Bottom Lock Catch LH		46.20	N?
9	1 pc	Tailgate Weatherstrip		195.20	Ntr
10	1 pc	Tailgate Outer Garnish LH		351.50	Ndew?
11	1 pc	Tailgate Opener Handle		143.60	Nx?
12	2 pcs	Tailgate Hinge LH	86.00	172.00	Nbt
13	1 pc	Tailgate Checker LH		72.00	N?
14	1 pc	Tailgate Inner Board		283.20	Nde
15	1 set	Tailgate Inner Board Clips		40.00	Nrei 20
16	1 pc	Tailgate RH		1,159.30	Nbt
17	1 pc	Tailgate Windscreen Inner Seal RH		60.00	Nrei
18	1 pc	Tailgate Emblem dci		69.60	Nrei
19	1 pc	Tailgate Inner Bottom Lock RH		136.20	Nx
20	1 pc	Tailgate Inner Bottom Lock Catch RH		58.00	Nx
21	1 pc	Tailgate Inner Rubber RH		139.20	Nrei
22	1 pc	Rear Bumper		790.00	Nde
23	2 pcs	Rear Bumper Side Retainers	39.00	78.00	N LH-dci, RHx
24	1 set	Rear Bumper Clips		50.00	N3 one
25	1 pc	Rear Bumper Sponge		119.60	Neng
26	1 pc	Rear Bumper Reflector LH		67.90	Nx
27	1 pc	Taillamp LH		289.50	N? pl. h.
28	1 pc	Taillamp Inner Sealer		38.00	N?
29	1 pc	End Panel		465.00	Nbt
30	1 pc	End Panel Top Trim		126.50	Nde
31	1 set	End Panel Top Trim Clips		30.00	Nrei
				7,001.90	
				Less 10%	700.19
				C/D	6,301.71

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : GBE 2560L

B/F

6,301.71

Special Nett

1	2 pcs	Tailgate Glass Sealant	60.00	120.00	80 net ✓
2	1 pc	Tailgate Sticker 70km/h		15.00	net ✓
3	1 pc	Tailgate Sticker 6pax		15.00	net ✓
4	1 set	Reverse Sensor		250.00	200 net ✓
5	1 set	Both Tailgate Company Logo		500.00	300 net ✓
6	1 set	Reverse Camera		450.00	x? photo

Labour charge

Panel Beating		1,000.00	700.
Spray painting		1,000.00	800.
Check Wiring		50.00	30.
Anti rust		120.00	50.
Remove and install both tailgate glass.		240.00	160.
Remove and install both tailgate parts.		180.00	140.
Remove and install carpet and interior.		120.00	60.
Remove and install reverse sensor		90.00	30.
Remove and install reverse camera		90.00	30.

10,541.71

Less 20% 2,108.34

Lump sum 8,433.37

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Kah 97495749

7/4/20 @ 245pm

Lump sum

Resurvey after repair

07 days

Tan Kah @ lkkauto.com