

Estimate

04/04/2020

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1

Veh # :- SLM8630T

Veh Model :- TOYOTA HARRIER ELEGANCE 2.0

Estimate# :- CK420594

Claim # :-

ACC. Date :- 02/04/20

Terms :- C.O.D Days

Remarks :-

Main Office:

Mova Building
No. 22, Jalan Kilang
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6476 3301
www.mova.com.sg

Workshop Dept:

Block 100B,
Bukit Merah Land 3,
401 04 000094
Singapore 150702
Tel: (65) 6272 3892
Fax: (65) 6270 0314
Co Reg: 1359010330
GST Reg: M2-00883612

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

LIST ITEMS :

1. REAR WINDSCREEN GLASS - T8A X n n
2. REAR WINDSCREEN GLASS MOULDING
3. TAILGATE
4. TAILGATE GARNISH
5. TAILGATE LOGO
6. TAILGATE EMBLEM - HARRIER
7. TAILGATE OUTER LAMP LH
8. TAILGATE OUTER LAMP RH
9. TAILGATE LOCK
10. TAILGATE LOCK COVER
11. TAILGATE LOCK ANTENNA SENSOR
12. TAILGATE RUBBER
13. TAILGATE INNER TRIM LOWER
14. TAILGATE INNER TRIM HANDLE LH
15. TAILGATE INNER TRIM HANDLE RH
16. TAILGATE STOPPER LH & RH X n n
17. TAILGATE ABSORBER LH - CHECK
18. TAILGATE ABSORBER RH - CHECK
19. TAILLAMP LH
20. TAILLAMP RH
21. TAILLAMP LOWER BRACKET LH
22. TAILLAMP LOWER BRACKET RH
23. TAILLAMP CLIP
24. REAR BUMPER
25. REAR BUMPER LOWER
26. REVERSE SENSOR
27. REAR BUMPER SIDE RETAINER LH
28. REAR BUMPER SIDE RETAINER RH
29. REAR BUMPER SPONGE
30. REAR BUMPER CLIP
31. END PANEL TOP GARNISH
32. END PANEL - REPAIR
33. SPARE TYRE PANEL - REPAIR ✓
34. TAILLAMP PANEL LH - REPAIR ✓
35. TAILLAMP PANEL RH - REPAIR ✓
36. REAR FENDER LH - REPAIR ✓
37. REAR FENDER RH - REPAIR ✓
38. REAR FENDER INNER TRIM LH ✓
39. REAR FENDER INNER TRIM RH ✓

LIST TOTAL S\$

25% DISCOUNT S\$

SPECIAL NET ITEMS :

1. SEALANT
2. REAR NUMBER PLATE

1	PC			
1	PC	75.00	✓	75.00 n e
1418.85	PC	2,125.00	✓	2,125.00 p e
	PC	555.00	✓	555.00 n e
	PC n e	59.00	✓	59.00 n e
	PC	75.00	✓	75.00 n e
	PC 412-90	498.00	✓	498.00 n e
	PC 412-80	498.00	✓	498.00 n e
	PC	435.00	✓	435.00 n e
	PC de	38.00	✓	38.00 n e
	PC	116.00	✓	116.00 n e
369.11	PC 412-90	442.00	✓	442.00 n e
568.50	PC 412-90	576.00	✓	576.00 n e
	PC	50.00	✓	50.00 n e
	PC de	50.00	✓	50.00 n e
	PCS	18.00	✓	36.00 n e
	PC			
	PC			
	PC			
	PC de	117.00	✓	117.00 n e
	PC	117.00	✓	117.00 n e
	PCS	6.00	✓	12.00 n e
	PC 1245-19	415.00	✓	415.00 n e
	PC de	465.00	✓	465.00 n e
	PC	376.00	✓	376.00 n e
	PC	93.00	✓	93.00 n e
	PC	93.00	✓	93.00 n e
	PC de	125.00	✓	125.00 n e
	PCS	5.00	✓	50.00 n e
423.10	PC de	445.00	✓	445.00 n e
	PC			
	PC			
	PC			
	PC			
	PC			
	PC 563-70	649.00	✓	649.00 n e
	PC 563-30	649.00	✓	649.00 n e
				10,334.00
				-2,553.50
				7,780.50
	PC	40.00	✓	40.00 n e
	PC	40.00	✓	40.00 n e



MOVA AUTOMOTIVE PTE LTD

Main Office:

Mova Building
No. 22, North Bridge Road
Singapore 05410
Tel: (65) 6476 3333
Fax: (65) 6476 3333
www.mova.com.sg

Workshop Dept:

21, North Bridge Road
Singapore 05410
Tel: (65) 6272 3892
Fax: (65) 6272 3892
GST Reg. No. 055894100

Estimate

04/04/2020

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1 138024

Veh # :- SLM8630T

Veh Model :- TOYOTA HARRIER ELEGANCE 2.0

Estimate# :- CK420594

Claim # :-

ACC. Date :- 02/04/20

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	SPECIAL NET TOTAL S\$			80.00
	LABOUR :			
	TO INSPECT REAR LIGHTING MECHANISM & CHECK WIRING	60	50.00	30.00
	TO REPLACE REVERSE SENSOR & DIAGNOSE FUNCTION	30	80.00	24.00
	TO REPAIR ON END PANEL, SPARE TYRE PANEL, BOTH TAILLAMP PANEL, REAR FENDER LH & RH. TO REPLACE DAMAGED ITEMS. REALIGN CONNECTION	700	900.00	630.00
	TO REMOVE & TRANSFER REAR WINDSCREEN GLASS INTO NEW TAILGATE	120	150.00	18.00
	TO REMOVE & REFIT REAR COMPARTMENT & FITTING	60	150.00	9.00
	TO SPRAY PAINT ON REPAIRED AREAS	700	1.00	0.70
	TO RUST PROOF ON REPAIRED AREAS	60	150.00	9.00
	TO APPLY BODY JOINT SEALANT ON REPAIRED AREAS	60	50.00	3.00
	LABOUR TOTAL S\$			743.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 10,620.50

GST @ 7 % 743.44

AMOUNT DUE S\$ 11,363.94

LYK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

Acknowledged by Repairer
Signature:
Date:

Taukh 97445719
WP 7/4/2020
6 days 340pm
tauikh@khant.com
Lumpsum 10%