

Estimate

04/04/2020

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1

Veh # :- SLM8630T

Veh Model :- TOYOTA HARRIER ELEGANCE 2.0

Estimate# :- CK420594

Claim # :-

ACC. Date :- 02/04/20

Terms :- C.O.D Days

Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1006,
 Bukit Merah Lane 3,
 #01-04, 00708, 94
 Singapore 159722
 Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR WINDSCREEN GLASS - TBA X nn	1	PC	
2.	REAR WINDSCREEN GLASS MOULDING	1	PC	75.00 ✓ 75.00 nn
3.	TAILGATE	1	PC	2,125.00 ✓ 2,125.00 nn
4.	TAILGATE GARNISH	1	PC	555.00 ✓ 555.00 nn
5.	TAILGATE LOGO	1	PC	59.00 ✓ 59.00 nn
6.	TAILGATE EMBLEM - HARRIER	1	PC	75.00 ✓ 75.00 nn
7.	TAILGATE OUTER LAMP LH	1	PC	498.00 ✓ 498.00 nn
8.	TAILGATE OUTER LAMP RH	1	PC	498.00 ✓ 498.00 nn
9.	TAILGATE LOCK	1	PC	435.00 ✓ 435.00 nn
10.	TAILGATE LOCK COVER	1	PC	38.00 ✓ 38.00 nn
11.	TAILGATE LOCK ANTENNA SENSOR	1	PC	116.00 ✓ 116.00 nn
12.	TAILGATE RUBBER	1	PC	442.00 ✓ 442.00 nn
13.	TAILGATE INNER TRIM LOWER	1	PC	676.00 ✓ 676.00 nn
14.	TAILGATE INNER TRIM HANDLE LH	1	PC	50.00 ✓ 50.00 nn
15.	TAILGATE INNER TRIM HANDLE RH	1	PC	50.00 ✓ 50.00 nn
16.	TAILGATE STOPPER LH & RH X nn	2	PCS	18.00 nn 36.00 nn
17.	TAILGATE ABSORBER LH - CHECK	1	PC	
18.	TAILGATE ABSORBER RH - CHECK	1	PC	
19.	TAILLAMP LH	1	PC	
20.	TAILLAMP RH	1	PC	
21.	TAILLAMP LOWER BRACKET LH	1	PC	117.00 ✓ 117.00 nn
22.	TAILLAMP LOWER BRACKET RH	1	PC	117.00 ✓ 117.00 nn
23.	TAILLAMP CLIP	2	PCS	6.00 nn 12.00 nn
24.	REAR BUMPER	1	PC	1,415.00 ✓ 1,415.00 nn
25.	REAR BUMPER LOWER	1	PC	465.00 ✓ 465.00 nn
26.	REVERSE SENSOR	1	PC	376.00 ✓ 376.00 nn
27.	REAR BUMPER SIDE RETAINER LH	1	PC	93.00 ✓ 93.00 nn
28.	REAR BUMPER SIDE RETAINER RH	1	PC	93.00 ✓ 93.00 nn
29.	REAR BUMPER SPONGE	1	PC	125.00 ✓ 125.00 nn
30.	REAR BUMPER CLIP	10	PCS	5.00 nn 50.00 nn
31.	END PANEL TOP GARNISH	1	PC	445.00 ✓ 445.00 nn
32.	END PANEL - REPAIR	1	PC	
33.	SPARE TYRE PANEL - REPAIR ✓	1	PC	
34.	TAILLAMP PANEL LH - REPAIR ✓	1	PC	
35.	TAILLAMP PANEL RH - REPAIR ✓	1	PC	
36.	REAR FENDER LH - REPAIR ✓	1	PC	
37.	REAR FENDER RH - REPAIR ✓	1	PC	
38.	REAR FENDER INNER TRIM LH ✓	1	PC	649.00 ✓ 649.00 nn
39.	REAR FENDER INNER TRIM RH ✓	1	PC	649.00 ✓ 649.00 nn
LIST TOTAL S\$				10,334.00
25% DISCOUNT S\$				-2,583.50
				7,750.50

SPECIAL NET ITEMS :

1.	SEALANT	1	PC	40.00	40.00 nn
2.	REAR NUMBER PLATE	1	PC	40.00	40.00 nn



Automotive Pte Ltd

Main Office:

Mova Building
No. 22 Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 3891
www.mova.com.sg

Workshop Dept:

Block 1008
Bukit Merah Lane 3,
#01-04/05/06/07
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6271 3891
Co. Reg: 196904033G
GST Reg: MO1068864-2

Page # :- 1 138024

Veh # :- SLM8630T

Veh Model :- TOYOTA HARRIER ELEGANCE 2.0

Estimate# :- CK420594

Claim # :-

ACC. Date :- 02/04/20

Terms :- C.O.D Days

Remarks :-

Estimate

04/04/2020

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

No.	Description	Qty	U.Price	Amounts S\$
	SPECIAL NET TOTAL S\$			80.00
	LABOUR :			
	TO INSPECT REAR LIGHTING MECHANISM & CHECK WIRING	60	80.00	80.00
	TO REPLACE REVERSE SENSOR & DIAGNOSE FUNCTION	30	80.00	80.00
	TO REPAIR ON END PANEL, SPARE TYRE PANEL, BOTH TAILLAMP PANEL, REAR FENDER LH & RH. TO REPLACE DAMAGED ITEMS. REALIGN CONNECTION	700	900.00	900.00
	TO REMOVE & TRANSFER REAR WINDSCREEN GLASS INTO NEW TAILGATE	120	150.00	150.00
	TO REMOVE & REFIT REAR COMPARTMENT & FITTING	60	150.00	150.00
	TO SPRAY PAINT ON REPAIRED AREAS	700 1000	1,200.00	1,200.00
	TO RUST PROOF ON REPAIRED AREAS	60	150.00	150.00
	TO APPLY BODY JOINT SEALANT ON REPAIRED AREAS	60	80.00	80.00
	LABOUR TOTAL S\$			2,790.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 10,620.50

GST @ 7 % 743.44

AMOUNT DUE S\$ 11,363.94

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

Acknowledged by Repairer

Signature:

Date:

Taukh 97495719
WP 7/4/202
6 days 340pm
tauakh@khant.com
Lumpsum 10%