

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20005002/GTF3E2

Date: 23/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLG520L

Insured Vehicle No : GBG8763T

Date of Loss: 03/04/2020

Nature of Claim: TP

Claim No: 5672427633SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG520L**

Make & Model: MAZDA 3, 1.6 (A)

Engine No: P520369658

Reg. Date: 19/09/2016 (Man. Year: 2016)

Chassis No: JM6BM42A8G0343624

Colour: Red

Odometer: 98233 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Continental 6 mm

Rear Left Side:

Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 06/04/2020

Date Inspected: 07/04/2020 Inspected At:

1 Kaki Bukit Ave 6 #02-39

Repairer : Dc's Automotive Pte Ltd

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Repair	0.00 F	*- F
2	1		*REAR RH FENDER	Repair	0.00 F	*- F
3	1		*REAR RH WHEEL RIM	Repair	0.00 F	*- F
					Total Parts (S\$)	0.00
						0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >