

Team AutoPro Pte Ltd 160 Sin Ming Dr, #02-12 Sin Ming AutoCity Singapore 575722

Tel: 8269-9999 Email: estimate.tap@gmail.com / teamautopl@gmail.com

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____ **After-Paint:** _____
 Contacts : _____

Vehicle Nos : **SML 3788 Z**
 Model : Hyundai Avante
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$	
1	Bonnet	1	\$ 1,052.00	\$ 1,052.00	DDV ✓
2	Bonnet lock	1	\$ 84.30	\$ 84.30	JAM ✓
3	Bonnet hinge	2	\$ 95.40	\$ 190.80	NDX
4	Front grille	1	\$ 683.20	\$ 460.20 683.20	BRV
5	Front grille logo	1	\$ 139.50	\$ 71.00 139.50	NECV
6	Front lisencc plate	1	\$ 120.50	\$ 69.00 120.50	BRV ✓
7	Front bumper	1	\$ 1,486.90	\$ 785.80 1,486.90	BRV
8	Front bumper lower lip	1	\$ 346.20	\$ 265.00 346.20	BT ✓
9	Front bumper rubber	1	\$ 84.30	\$ 84.30	TN ✓
10	Front bumper side retainer	2	\$ 86.90 159.40	\$ 173.80 318.80	NECV
11	Front bumper fog lamp	2	\$ 386.10	\$ 772.20	NNX
12	Front bumper fog lamp cover	2	\$ 106.50	\$ 213.00	NNX
13	Front bumper inner sponge	1	\$ 264.70	\$ 264.70	BRV ✓
14	Front bumper reinforcement	1	\$ 652.80	\$ 589.50 652.80	DDV
15	Headlamp	2	\$ 1,893.50	\$ 3,787.00	BRV
16	Headlamp lower bracket	2	\$ 98.60 214.30	\$ 197.20 428.60	BRV
17	Front support panel	1	\$ 859.50	\$ 859.50	BRV
18	Front support panel top garnish	1	\$ 204.00	\$ 204.00	NSX
19	Air con condensor	1	\$ 947.60	\$ 819.60 947.60	BRV
20	Radiator	1	\$ 865.20	\$ 561.90 865.20	BT ✓
21	Front fender	LH 1	\$ 785.60	\$ 785.60 1,571.20	DDV ✓
22	Front fender inner cowling	RH 1	\$ 284.60	\$ 195.70 569.20	TN ✓
Parts Sub Total :				\$ 11,106.10	15,641.50
20% Discount				\$	3,128.30
PARTS TOTAL :				\$ 8,884.88	12,513.20

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00 80.00
2	Bonnet sealant	1	\$ 100.00	\$ 30.00 100.00
3	Bonnet insulator clip	1	\$ 50.00	\$ 30.00 50.00
4	Front bumper clip	1	\$ 50.00	\$ 30.00 50.00
5	Front grille clip	1	\$ 50.00	\$ 30.00 50.00
6	Air con fluid	1	\$ 80.00	\$ 40.00 80.00
7	Radiator coolant	1	\$ 80.00	\$ 50.00 80.00
8	Front support panel top garnish clip	1	\$ 50.00	\$ 50.00
9	Front fender sealant	2	\$ 100.00	\$ 100.00 200.00
10	Front fender inner cowling clip	2	\$ 50.00	\$ 30.00 100.00
11	Front number plate w/ cowling	1	\$ 80.00	\$ 50.00 80.00
SPECIAL NETT TOTAL :				\$ 360.00 920.00

NNT
 NEC ✓
 -NNT
 NEC ✓
 NNT
 NEC ✓

Nos.	LABOUR	S\$
1	Panel beating	\$ 1200.00 1,800.00
2	Spray paint	\$ 1000.00 1,600.00
3	R&R Radiator	\$ 80.00 150.00
4	R&R Air con condensor	\$ 80.00 150.00
5	Upholstery	\$ 200.00
6	check wiring	\$ 60.00 100.00
LABOUR TOTAL :		\$ 2420.00 4,000.00

✓
 ✓
 ✓
 ✓
 NNT ✓

Survey 8/4/2020
 TGLim
 1300 hrs

Resurvey 9/4/2020
 TGLim
 1430 hrs
 Part by Part repair
 Repair days 9

PARTS TOTAL : \$ 8884.88 12,513.20
 SPECIAL NETT TOTAL : \$ 360.00 920.00
 LABOUR TOTAL : \$ 2420.00 4,000.00
GRAND TOTAL : \$ 11,664.88

TGLim
 16/4/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date: