

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHC 5825T

AAD2004-011

*Not Authored**Hong & 325/*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

06 APR 2020

SHC 5825T

VF1ABL15AUC280332

RENAULT

LATITUDE

1.4.2020

TOKIO MARINE

11/12/2014

PART		LIST	
1	BUMPER COVER FRT	\$	747.20
1	BUMPER SPOILER FRT	\$	344.70
1	BUMPER ABSORBER FRT	\$	394.68
1	BUMPER RETAINER FRT LH	\$	101.40
1	BUMPER RETAINER FRT RH	\$	101.40
1	BUMPER UNDERTRAY FRT	\$	292.50
1	BUMPER GRILLE LOWER FRT	\$	147.00
1	BUMPER FOG LAMP GRILLE LH	\$	207.21
1	BUMPER FOG LAMP GRILLE RH	\$	207.21
1	BUMPER BEAM FRT	\$	663.70
1	TOW COVER FRT	\$	60.90
1	FRONT BRACE PANEL	\$	177.22
1	RADIATOR GRILLE	\$	969.90
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	225.36
1	RADIATOR GRILLE FRAME	\$	686.00
1	FRAME FULL SUPPORT PANEL	\$	592.70
1	FRAME FULL SUPPORT BRACKET	\$	41.60
1	HEADLAMP LH	\$	743.60
1	HEADLAMP RH	\$	743.60
1	HEADLAMP PANEL FRT LH	\$	127.70
1	HEADLAMP PANEL FRT RH	\$	128.30
1	BONNET	\$	1,312.70
1	BONNET INSULATOR	\$	294.30
1	BONNET STRUT LH	\$	53.30
1	BONNET STRUT RH	\$	53.30

X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5825T**AAD2004-011**

1	BONNET HINGE LH	\$	236.50	}	X	
1	BONNET HINGE RH	\$	237.40			
1	BONNET LOCK	\$	152.80			
1	FENDER PANEL FRT LH	\$	414.40			
1	WHEELARCH FRT LH	\$	112.30			
1	FENDER BRACKET LOWER LH	\$	11.80			
1	FENDER PANEL FRT RH	\$	437.10			
1	WHEELARCH FRT RH	\$	191.40			
1	FENDER BRACKET LOWER RH	\$	11.80			
1	WIPER RESERVOIR	\$	179.60			
1	WIPER RESERVOIR NECK	\$	29.30			
1	WIPER RESERVOIR MOTOR	\$	82.60			
1	AIR CLEANER BOX	\$	464.20			
1	AIR CLEANER HOSE	\$	175.85			
1	AIR CLEANER LOWER	\$	271.26			
TOTAL		\$	12,425.79			
10%		\$	1,242.58			
		\$	11,183.21			

Special Nett

1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	}	X
1SET	BUMPER CLIP FRT	\$	66.00		
1SET	BUMPER BRACKET CLIP FRT LH	\$	12.00		
1	BUMPER SUPPORT CLIP FRT LH	\$	10.50		
1	BUMPER BRACKET CLIP FRT RH	\$	12.00		
1	BUMPER SUPPORT CLIP FRT RH	\$	10.50		
1	RADIATOR GRILLE SCREW	\$	16.00		
1SET	BUMPER GRILLE LOWER CLIP	\$	69.00		
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00		
1SET	FRAME FULL SUPPORT PANEL NUT	\$	20.00		
2	FRAME FULL SUPPORT PANEL STUD	\$	30.00		
1	FRONT RENAULT TYRE 215/60/16	\$	300.00		
1	FRONT RENAULT TYRE RIM	\$	380.00		

AAD2004-011

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5825T

- 1 Front licence plate with holder
 1SET WHEELARCH CLIP FRT LH
 1SET WHEELARCH CLIP FRT RH

\$	B1	80.00	455n-
\$	nn	30.50	X
\$	nn	30.50	X
TOTAL	\$	1,189.00	

TOTAL PARTS \$ **12,372.21**

Labour

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		6,000.00	601
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To Transfer Of Front Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn	170.00	X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To rust-proofing of the affected areas.	\$	nn	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X

Trans-cab Auto Services Pte Ltd

AAD2004-011

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5825T

To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00 <i>X</i>
Putty and spray painting of the affected portion.	\$	6,000.00 <i>2201</i>
TOTAL	\$	14,000.00
Over All Total	\$	26,372.21

(LUMP SUM) Repair Days

*20 DAYS**1 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: