



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

07-04-2020

TP Alh.

Khanchan

Accident date: 06/04/2020

Estimated repair cost for vehicle no: SLR9326P SUBARU IMPREZA 5D 1.6A '17

CHASSIS: JF1GT3KC5HG009355

S/n	Qty	Items	U/price	Amount	
1	1	Rear L/H Door <i>Dented.</i>		\$684.60	✓
2	2	Rear L/H Door Hinge <i>NH m</i>	\$48.30	\$96.60	✗
3	1	Rear L/H Door Lock <i>NH m</i>		\$206.50	✗
4	1	Rear L/H Door Weatherstrip <i>NH m</i>		\$146.20	✗
5	2	Rear L/H Door Framesticker <i>NH</i>	\$49.80	\$99.60	✓
6	1	Rear L/H Door Inner Trim Board <i>NH m</i>		\$621.90	✗
7	1	Rear L/H Door Window Regular & Motor Assy <i>NH m</i>		\$292.30	✗
8	1	Rear L/H Fender <i>Dented</i>		\$1,018.40	✓
9	1	Rear L/H Fender Glass Assy <i>gaw m</i>		\$396.00	✗
10	1	Rear L/H Fender Cowling		\$62.20	✗
11	8	Rear L/H Fender Cowling Clip <i>NH m</i>	\$6.50	\$52.00	✗
12	1	Rear L/H Lower Arm <i>Bent</i>		\$492.20	✓
13	1	Rear L/H Upper Arm <i>Bent</i>		\$648.90	✓
14	1	Rear L/H Knuckle Arm <i>Dented</i>		\$545.20	✓
15	1	Rear L/H Knuckle Arm Bearing <i>Dented</i>		\$202.20	✓
16	1	Rear L/H Trailing Arm <i>Bent</i>		\$140.90	✓
17	1	Rear L/H Control Arm <i>Bent</i>		\$195.70	✓
18	1	Rear L/H Shock Absorber <i>(After Market) Bent.</i>	\$500	\$1,000	450 (SV)
19	1	Rear L/H Stabilizer Bar <i>gaw</i>		\$281.60	✗
20	1	Rear L/H Driveshaft <i>gaw</i>		\$883.20	✗
21	1	Rear L/H Tyre <i>NH m</i>		\$380.00	✗
22	1 set	Sport Rim <i>Bent</i>		\$2,500.00	650 (SV)
23	1	L/H Rocker Panel Side Skirt <i>conced</i>		\$708.00	✓
24	2	Rear Taillamp <i>cut LH</i>	\$392.80	\$785.60	392.80
25	4	Rear Taillamp Clip <i>m</i>	\$8.00	\$32.00	10
26	1	Rear Boot Lid <i>Regis</i>		\$976.40	✗
27	1	Rear Boot Lid Emblem Logo <i>gaw</i>		\$70.60	✓
28	1	Rear Boot Lid Subaru Logo		\$75.80	✓
29	1	Rear Boot Lid AWD Logo		\$58.00	✓

30	1	Rear Boot Lid Impreza Logo	new		\$65.00	✓
31	1	Rear Boot Lid Lock	2nd		\$176.40	✓
32	1	Rear Boot Lid Weatherstrip	new		\$116.00	✓
33	1	Rear Boot Lid Windscreen Moulding	new		\$83.50	✓
34	1	Rear Bumper	Deformed		\$643.90	✓
35	10	Rear Bumper Clip	new	\$6.50	\$65.00	30
36	2	Rear Bumper Side Retainer	new	\$22.90	\$45.80	✓
37	2	Rear Bumper Side Reflector	new	\$34.80	\$69.60	✓
38	1	Rear Bumper Towing Cover	new		\$26.00	✓
39	1	Rear Bumper Reverse Sensor	2nd		\$380.00	200/sv
40	1	Rear Bumper Reinforcement	Bent		\$382.80	✓
41	1	Rear End Panel	Repair		\$335.80	✓
42	1	Rear End Panel Top Garnish	Deformed		\$157.80	✓

Subtotal :- \$15,423.90

6874.7 SN. 1300
5499.76.

Labour charges

To remove & refit cushion & trim board	\$280.00	80
To remove & refit rear windscreen	\$120.00	x
Gum	\$60.00	x
To remove & refit rear L/H fender glass	\$100.00	x
Gum	\$50.00	x
To remove & refit rear reverse sensor	\$120.00	50
To remove & refit rear reverse camera	\$180.00	x
To remove & refit rear undercarriage	\$450.00	220
To remove & refit rear L/H door & components	\$280.00	80
To check wheel alignment	\$150.00	80
To check wiring	\$100.00	30
Towing fee	\$150.00	x
Tuff kote	\$150.00	50
Panel beating	1100	\$1,800.00
Spray painting		\$2,000.00

Subtotal :- \$5,990.00

Total:- \$21,413.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total 9389.76

4/s 7.51C

07 Days

7.51C

07 Days