

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

AUTOEXCEL ENGINEERING PTE LTD
160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591630
Fax: 64591698

Not Authorized
Refusing B4 painting

4 days

L1 Surp & 4700

4500

Date : 07/04/2020

QUOTATION -THIRD PARTY CLAIM

EQ INSURANCE COMPANY LTD

Attn: Motor Claim Department . Officer In Charge

Accident on : 06/04/2020

Claim : Third Party Claim
Veh. No : SCR 8398 U
Model :
Insured Ins: MERCEDES C180
GST Reg. No : 19 - 9603355 - R

QTY	PARTICULARS	AMOUNT	SURVEYOR
	Your Insurer Vehicle No : SGM 4194 X		
1	BOOTLID	REPAIR	
1	BOOTLID LOCK 399.20	\$ 680.00	2
1	BOOTLID WEATHERSTRIP	\$ 488.50	X
1	BOOTLID CENTER LOGO 85	\$ 120.00	—
1	BOOTLID C 180 EMBLEM 82	\$ 98.00	—
1	BOOTLID CC EMBLEM 45	\$ 180.00	—
1	9 G - TRONIC EMBLEM 60	\$ 95.00	—
2	TAILLAMPS C 785.90	\$ 2,250.00	4
2	TAILLAMP LOWER BRACKETS	\$ 780.00	2
1	BOOTLID LOWER LOCK SENSOR	\$ 558.00	X
1	END PANEL	\$ 1,480.00	X
1	END PANEL TOP GARNISH	\$ 580.00	X
1	REAR BUMPER CMT / Bm	\$ 1,285.00	—
10	REAR BUMPER CLIPS	\$ 45.00	—
2	REAR BUMPER SIDE RETAINERS	\$ 480.00	X
1	REAR BUMPER REINFORCEMENT	\$ 650.00	2
1	REAR BUMPER SPONGE	\$ 445.00	2
15	REAR BUMPER RIVETS C 5.00	\$ 300.00	75
1	REAR BUMPER CENTER BRACKET	\$ 580.00	X
1	REAR BUMPER LOWER GARNISH 570	\$ 785.60	—
1	REAR BUMPER LOWER CHROME 260	\$ 620.00	—
1	REAR BUMPER LOWER COVER	\$ 550.00	X
2	REAR BUMPER SENSORS C 245	\$ 660.00	2
3	REAR BUMPER SENSOR RIM C 72	\$ 540.00	2 216
1SET	REAR BUMPER SENSOR CABLE	\$ 560.00	X
1	FRONT DRIVER SEAT BELT	\$ 680.00	X
1	FRONT DRIVER SEAT BELT ECU	\$ 1,850.00	X
	TOTAL :	\$ 17,340.10	
	LESS 10%	\$ 15,606.09	
	Total Parts :	\$ 15,606.09	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTOEXCEL ENGINEERING PTE LTD

160, Sin Ming Drive
Sin Ming Auto City #06-15
Singapore 575722
Tel: 64535654, 64591639
Fax: 64591698

Balance b/f	\$ 15,606.09	
<u>LABOUR CHARGES</u>		
Labour charges, to do cutting, welding, replace repair accident affected area	\$ 1,200.00	3001
To remove refix , replace garnish, trim, upholstery etc	\$ 300.00	601
To do computer setting after repair <i>nn</i>	\$ 300.00	X
To check wiring system on accident area	\$ 180.00	201
Anti rust <i>nn</i>	\$ 120.00	X
To do spray painting on accident affected area	\$ 800.00	3001
To replace rear exhaust <i>nl</i>	\$ 280.00	X
Total Labour :	\$ 3,180.00	
TOTAL PARTS & LABOUR :	\$ 18,786.09	