

NOT Authorized

Call @ 21,000h
Purabaya, Aka Peim

Belas

TO	: AXA	DATE	: 6-Apr-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT :			
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	SML4612R
ADDRESS	:	MODEL	PORCHE PANAMERA
TEL. NO.	:	CHASSIS NO	
OWNER'S INSURANCE :			
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT :			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/ N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SIDE MIRROR RH <i>Sm</i>	1	\$ 1,598.00	\$ 1,598.00
2	FRONT DOOR RH <i>3404.49 CM</i>	1	\$ 6,598.20	\$ 6,598.20
3	FRONT DOOR INNER LOCK RH	1	\$ 598.00	\$ 598.00
4	FRONT DOOR OUTER HANDLE RH <i>375 ND</i>	1	\$ 499.00	\$ 499.00
5	FRONT DOOR OUTER MOULDING RH <i>Sm</i>	1	\$ 259.00	\$ 259.00
6	REAR DOOR RH <i>3766.49 B1</i>	1	\$ 6,112.00	\$ 6,112.00
7	REAR DOOR INNER TRIM BOARD RH <i>Sm</i>	1	\$ 1,359.00	\$ 1,359.00
8	REAR DOOR INNER LOCK RH <i>R</i>	1	\$ 598.00	\$ 598.00
9	REAR DOOR REGULATOR C/W MOTOR RH <i>Sm</i>	1	\$ 1,985.00	\$ 1,985.00
10	REAR DOOR OUTER HANDLE RH <i>375 ND</i>	1	\$ 499.00	\$ 499.00
11	REAR DOOR OUTER MOULDING RH <i>Sm</i>	1	\$ 259.00	\$ 259.00
12	REAR BUMPER <i>2663.33 CM</i>	1	\$ 5,894.00	\$ 5,894.00
13	REAR BUMPER SIDE RETANEL RH <i>D/I</i>	1	\$ 345.00	\$ 345.00
14	RIGHT SIDE WHEEL CARRIER <i>B1 B2</i>	1	\$ 1,654.00	\$ 1,654.00

X
✓
X
✓
X
✓
X
X
✓
X
✓
✓
✓
✓
✓

15	REAR FENDER RH	4258	B1	1	\$ 6,542.00	\$ 6,542.00	✓
16	REAR FENDER COWLING HR		B1	1	\$ 456.00	\$ 456.00	X
17	TAILAMP RH		B1	1	\$ 2,159.00	\$ 2,159.00	X
18	SIDE SKIRT		B1	1	\$ 3,458.00	\$ 3,458.00	X
19	REAR WHEEL ALLOY SPORT RIM RH	2850	B1	1	\$ 6,584.00	\$ 6,584.00	✓
20	REAR SHOCK ABSORBER RH		B1	1	\$ 1,295.73	\$ 1,295.73	✓
21	REAR SHOCK ABSORBER MOUNT RH		B1	1	\$ 554.00	\$ 554.00	X
22	REAR SHOCK ABSORBER BASE RH		B1	1	\$ 258.00	\$ 258.00	X
23	REAR SHOCK ABSORBER WASHER RH		B1	1	\$ 48.00	\$ 48.00	X
24	REAR SHOCK ABSORBER ADDITIONAL SPRING			1	\$ 195.60	\$ 195.60	X
25	REAR SHOCK ABSORBER BELOW RH		B1	1	\$ 258.00	\$ 258.00	X
26	REAR LOWER ARM RH		B1	1	\$ 1,355.00	\$ 1,355.00	X
27	REAR UPPER ARM RH		B1	1	\$ 541.00	\$ 541.00	X
28	REAR WHEEL HUB RH		B1	1	\$ 517.59	\$ 517.59	X
29	REAR WHEEL HUB BEARING RH		B1	1	\$ 224.10	\$ 224.10	X
30	REAR WHEEL HUB SCREW RH		B1	4	\$ 45.00	\$ 180.00	X
31	REAR WHEEL HUB SCREW COVER RH		B1	1	\$ 41.20	\$ 41.20	X
32	REAR TIE ROD RH		B1	1	\$ 645.00	\$ 645.00	X
33	REAR CONTROL ARM RH	1755	D1	1	\$ 1,845.00	\$ 1,845.00	✓
34	REAR STONEGUARD FILM RH		B1	1	\$ 312.00	\$ 312.00	✓

108

TOTAL PRICE \$55,726.42
 LESS 0% \$ -
 SUB TOTAL PRICE \$55,726.42

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP	1	\$ 60.00	\$ 60.00
2	TAIL LAMP CLIP	1	\$ 60.00	\$ 60.00
3	SIDE SKIRT CLIPS	1	\$ 60.00	\$ 60.00
4	REAR WHEEL TYRE RH	1	\$ 1,200.00	\$ 1,200.00
TOTAL				\$ 1,380.00

✓
 X
 X
 409.00 480.00

SN	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, WELD, CUT, ADJUST	\$2,500.00	1200	
2	TO PUTTY, SPRAY PAINT, POLISH WA	\$1,600.00	1400	

3	TO SPRAY TUFF COAT	\$ 400.00	301
4	CONDUCT WATER LEAKAGE TEST UP	\$ 180.00	301
5	REMOVE AND REFIX RAER UNDERCA	\$ 650.00	2801
6	FOUR WHEEL ALIGNMENT CHARGES	\$ 300.00	1201

TOTAL \$ 5,630.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 57,106.42
TOTAL LABOUR COST : \$ 5,630.00
TOTAL REPAIR COST \$ 62,736.42

APPROVED DETAILS

EXCESS :
NO. OF DAYS : 8 days
RE-SURVEY : Yes

PART BY PART OR LUMP SUM

DATE & TIME OF SURVEY : 7/4/20 2.30pm
SURVEYED BY : Kenneth
CONTACT NUMBER : 96910663
FAX NUMBER :

KennethKong@kkquto.com