

ASS. REC. BY:

REF: C72 / CS/CTI20005044/Kqf3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. DMPCSN30545219000

Claims No. SNM20D201672C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: 1pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SKX 57E Yr Regn: 11, 15

Type: M.Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or AI

Make: Mazda 3 c.c. 1488

Colour: M.P. Red A/C: Insured / Std / NI / NA

Sp. Reading: 42470 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM 8BM 42A8G 0323414

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 3/4/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S M

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

25/11/20 @ 2.21pm checked with Mui Hong, the vehicle has not send in repair

25/11/20 @ 2.27pm revised to Tan Kah Leong via Merimen.

25/11/20 Submit Preli. report.

Date/Time, File Pass to?



Preli. Report

1) 25/11 Typist



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trlp: \_\_\_\_\_

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech Invs (\$☐ Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

## SURVEYOR COPY

M/S : ONG BOON WAH, DANIEL  
57 LIMBOK TERRACE

SINGAPORE 545202

ATTN:

Estimate No: MC1901159  
Date: 06 Apr 2020  
Policy No: P1847233  
Veh Reg No: SKX57E  
Make/Model: MAZDA MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 03/04/2020  
TP Veh Reg No: SKP7025T

### Estimate Repair Cost to Vehicle No :SKX57E

| Description                                                                                                                                                   | Quantity | List Price | Amount      |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|-------------|
|                                                                                                                                                               |          | SS         | SS          |
| <b>SPARE PARTS</b>                                                                                                                                            |          |            |             |
| 1 HEADLAMP RH                                                                                                                                                 | 1 PC     | 2,357.30   | X           |
| 2 FRONT BUMPER                                                                                                                                                | 1 PC     | 1,083.30   | X           |
| 3 FRONT BUMPER SIDE RETAINER RH                                                                                                                               | 1 PC     | 19.70      | X           |
| 4 FRONT BUMPER CLIPS                                                                                                                                          | 10 PC    | 30.00      | X           |
|                                                                                                                                                               |          | 3,490.30   |             |
|                                                                                                                                                               | Less 20% | 698.06     | 2,792.24    |
| <b>LABOUR</b>                                                                                                                                                 |          |            |             |
| 5 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING. | 1 PC     | 40.00      | 101         |
| 6 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR FRONT FENDER RH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.          | 1 PC     | 400.00     | 250         |
| 7 TO SPRAY FRONT BUMPER, FRONT FENDER RH.                                                                                                                     | 1 PC     | 450.00     | 400         |
|                                                                                                                                                               |          | 890.00     | 890.00      |
| Total                                                                                                                                                         |          |            | SS 3,682.24 |
| Add GST @ 7%                                                                                                                                                  |          |            | 257.76      |
| Total Amount Payable                                                                                                                                          |          |            | SS 3,940.00 |

TOTAL: SINGAPORE DOLLAR THREE THOUSAND NINE HUNDRED FORTY ONLY

Please arrange this vehicle to be surveyed soonest possible.  
Thank You

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

**DETAILS OF OWN VEHICLE**

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SKX57E               |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | ONG BOON WAH, DANIEL |
| NRIC No                     | SXXXX138E            |
| Email Address               | DOBW1973@GMAIL.COM   |
| Mobile Phone No             | (LOCAL) +65-96818834 |
| Alternative Phone No        | OTHERS-96818834      |

**Vehicle Particulars**

|                                                                              |                                  |
|------------------------------------------------------------------------------|----------------------------------|
| Manufacturer                                                                 | MAZDA                            |
| Model                                                                        | MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE                      |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                               |
| If No, Please state action to be taken                                       | THIRD PARTY                      |
| Vehicle Category                                                             | PRIVATE CAR                      |

**Insurance Company**

|                           |                         |
|---------------------------|-------------------------|
| Name of Insurance Company | AXA INSURANCE PTE LTD   |
| Type Of Coverage          | COMPREHENSIVE           |
| Fleet Policy              | NO                      |
| Policy Number             | P1847233                |
| Cover Note Number         | 12/11/2019 - 11/11/2020 |

**Driver**

|                      |                       |
|----------------------|-----------------------|
| Name of Driver       | ONG BOON WAH, DANIEL  |
| NRIC No              | SXXXX138E             |
| Date Of Birth        | 14/08/1973            |
| Occupation           | INDOOR                |
| Date Of Driving Pass | 16/10/1992            |
| Driving Experience   | 27 YEARS AND 5 MONTHS |
| Gender               | MALE                  |
| Mobile Number        | (LOCAL) +65-96818834  |
| Fax Number           |                       |
| Contact Number       | OTHERS-96818834       |
| Email Address        | DOBW1973@GMAIL.COM    |