Attn:

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building

78 Shenton Way #08-16 Singapore 079120

Azlan, Syazairdina

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Date: 08 Apr 2020

## **Preliminary Advice**

Vehicle No Accident Date : 30/03/2020 : SJJ318M Make : AUDI Q5 SPORT Policy No. : 1800067098 : 07/04/2020 Excess Assignment Date : S\$0.00 Date of Inspection : 06/04/2020 Est. Duration of Repair : 3.00

Inspection At : PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1 SINGAPORE 408699

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 25,212.00 |
|-----------------------------|------|-----------|
| Revised Amount              | :S\$ | 8,181.00  |
| Check Items (Estimated)     | :S\$ | 11,130.00 |
| Total                       | :S\$ | 19,311.00 |

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 154,000.00 COE / PARF Rebate :S\$ 70,662.00

Salvage Value :S\$

Margin for Repair :S\$ 83,338.00

### Remarks

| ( X | ) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. |
|-----|---|---------------------------------------------------------------------------------------------------------------------------------------------|
| (   | ) | The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.                                                 |
| (   | ) | Other comments :                                                                                                                            |