



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

07-04-2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAXA.
Jasper

Accident date: 06/04/2020

Estimated repair cost for vehicle no: SMK7220Z HYUNDAI AVANTE 1.6 A '19

CHASSIS: KMHD841CMKU893845

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Dented.</i>		\$1,853.00	✓
2	2	Rear Boot Lid Hinge <i>Not nec</i>	\$65.10	\$130.20	x
3	1	Rear Boot Lid Emblem Logo <i>3 nec</i>		\$68.90	✓
4	1	Rear Boot Lid Avante Emblem Logo		\$80.30	✓
5	1	Rear Boot Lid Reverse Camera <i>Not NEC</i>		\$680.00	x
6	1	Rear Boot Lid Lock <i>Damaged</i>		\$145.70	✓
7	1	Rear Boot Lid Weatherstrip <i>cut</i>		\$145.60	✓
8	1	Rear Boot Lid Trimboard <i>Not nec</i>		\$195.80	x
9	10	Rear Boot Lid Trimboard Clip <i>Not nec</i>	\$6.50	\$65.00	x
10	2	Rear Boot Lid Side Reflector <i>cut</i>	\$489.70	\$979.40	✓
11	2	Rear Boot Lid Side Reflector Sticker <i>Not nec</i>	\$80.00	\$160.00	x
12	2	Rear Taillamp <i>cut</i>	\$545.60	\$1,091.20	✓
13	4	Rear Taillamp Clip <i>Not nec</i>	\$8.00	\$32.00	20
14	2	Rear Taillamp Sticker <i>Not nec</i>	\$80.00	\$160.00	x
15	1	Rear Bumper <i>Deformed</i>		\$654.30	✓
16	10	Rear Bumper Clip <i>Not nec</i>	\$6.50	\$65.00	30
17	2	Rear Bumper Side Retainer <i>Not nec</i>	\$85.90	\$171.80	✓
18	1	Rear Bumper Garnish <i>cut</i>		\$496.30	✓
19	2	Rear Bumper Garnish Side Reflector <i>cracked</i>	\$305.70	\$611.40	✓
20	1	Rear Bumper Number Plate <i>Not nec</i>		\$50.00	x
21	2	Rear Bumper Number Plate Lamp <i>Not nec</i>	\$39.40	\$78.80	x
22	1	Rear Bumper Reverse Sensor <i>Damaged</i>		\$380.00	200(SN)
23	1	Rear Bumper Reinforcement <i>cracked.</i>		\$489.30	345
24	2	Rear Bumper Reinforcement Side Bracket <i>Not nec</i>	\$294.80	\$589.60	x
25	3	Rear Bumper Reinforcement Top Bracket Holder <i>Not nec</i>	\$35.00	\$105.00	x
26	2	Rear Fender Inner Trim Board <i>3 nec</i>	\$285.90	\$571.80	x
27	16	Rear Fender Inner Trim Board Clip <i>3 nec</i>	\$6.50	\$104.00	x
28	1	Rear End Panel <i>Dented</i>		\$657.80	✓
29	1	Rear End Panel Top Garnish <i>Deformed</i>		\$175.90	✓

30	1	Rear End Panel Buzzer	3 all m	\$285.70 ⁺
31	1	Rear Spare Tyre Panel		\$745.80 ^x
32	1	Rear Spare Tyre Panel Top Cover	3 all m	\$385.90 ^x
33	1	Rear Spare Tyre Panel & End Panel Sealant		\$450.00 ^x
34	1	Ceramic Coating	Noc	\$850.00 ^x
				400 (SN)
				760860 3w 600
				600688
Subtotal :-				\$13,705.50

Labour charges

To remove & refit cushion & trim board

~~\$280.00~~ 80

To remove & refit rear reverse sensor

~~\$100.00~~ 60

To remove & refit reverse camera

~~\$180.00~~ 60

To check wiring

~~\$100.00~~ 30

Towing fee

~~\$150.00~~ x

Tuff kote

~~\$150.00~~ 60

Panel beating

~~\$1,400.00~~ 800

Spray painting

~~\$1,200.00~~ 800.

Subtotal :- \$3,560.00

Total:- \$17,265.50

total 8496.88
1/s 6.8K
06 Days

6.8K
06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: