



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2105621  
INV Date 11/08/2021  
Reference CC6/LPC20005064/Aba3q2  
Code LPC2

#### PROFESSIONAL SERVICE FEE

Vehicle No. SLR 6219K  
Insured Veh. SKB 8743X  
Claim No. 20/20/20/VP05/023299  
Policy No. Z20VP05025677  
Accident Date 06/04/2020  
Inspection Date 07/04/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

**LKM**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: CC6/LPC20005064/Aba3q2

Date: 11/08/2021

Code: LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SKB 8743X	<b>Veh. Inspected</b>	SLR 6219K
<b>Policy No.</b>	Z20VP05025677	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	20/20/20/VP05/023299	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	KENNY	<b>Assign Date</b>	07/04/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MITSUBISHI LANCER	<b>c.c</b>	1584
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	JMYSNCS3A9U003255	<b>Colour</b>	BLACK
<b>Odometer</b>	332073 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	195/50 R15	GOODRICH	6 mm
<b>L/H Front Tyre</b>	195/50 R15	GOODRICH	6 mm
<b>R/H Rear Tyre</b>	195/50 R15	GOODRICH	6 mm
<b>L/H Rear Tyre</b>	195/50 R15	GOODRICH	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	06/04/2020	<b>Inspection Date</b>	07/04/2020
<b>Survey held at</b>	ADVANCE AUTO GARAGE 10 KAKI BUKIT ROAD 2 #03-01 FIRST EAST CENTRE SINGAPORE 417868		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 6219K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	DISTORTED	723.00	723.00
1	FRONT BUMPER CLIPS	NECESSARY	30.00	30.00
2	FRONT BUMPER SIDE HOLDER @\$41.00	O/S NECESSARY	82.00	41.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	289.00	-
1	HEADLAMP RH	CUT	586.00	586.00
1	BONNET LOCK	NOT NECESSARY	48.00	-
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	486.00	-
	LESS 10% DISCOUNT		-	-138.00
			2,244.00	1,242.00
<b>SPECIAL NETT ITEMS</b>				
1	FRONT BUMPER LOWER SPOILER (SN)	TO REPAIR SEE LABOUR	1,200.00	-
1	FRONT GRILLE (SN)	NOT NECESSARY	480.00	-
1	FRONT GRILLE LOGO (SN)	NOT NECESSARY	40.00	-
1	BONNET (CARBON FIBER)(SN)	CRACKED	2,000.00	1,800.00
1	BODY WRAP STICKER (SN)	NECESSARY	2,000.00	1,250.00
			5,720.00	3,050.00
<b>LABOUR</b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BUMPER LOWER SPOILER AND FRONT RH FENDER .		800.00	400.00
	SPRAY PAINTING .		1,000.00	600.00
	WIRING .		50.00	30.00
			1,850.00	1,030.00
<b>GRAND TOTAL</b>			<b>9,814.00</b>	<b>5,322.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,600.00</b>

Report Ref No. CC6/LPC20005064/Aba3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



# LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## PHOTOGRAPHS FOR VEHICLE NO. SLR 6219K

## INSPECTION






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLR 6219K

RE-INSPECTION

