

SLR6219K 2009 Feb.

Mitsubishi Lancer 1584 cc  
JMYSNCS3A9U003255

Vic

Front Bumper	Distanted	723	✓
Front Bumper Clips	m	30	✓
Front Bumper Side Holder x 02	RH New	<del>41 x 2 = 82</del>	x 41
Front Bumper Reinforcement	new	289	x
Front Bumper Lower Spoiler	Reps	1200 (SN)	x
Front Grille	3 x m	480 (SN)	x
Front Grille Logo	1 m	70 (SN)	x
Headlip RH	at	586	✓
Bonnet (Carbon Fiber)	could	<del>2000 (SN)</del>	1200 (SN)
Bonnet lock	new	48	x
Front RH Fender	Reps	486	x
Body Wrap Sticker	new	<del>2000 (SN)</del>	1250 (SN)

1380

S.N 1250.

1242

Panel Beating		<del>800</del>	400
Spray Painting	1030	<del>1000</del>	600
Wiring		<del>50</del>	30

total. 4522

L/S: 3.6k.

06 Days.

3.6k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

ABC