

Our Job Ref No 305392160
Date 23.04.20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax : _____
Attn : Mr TAUFIKH
Vehicle Reg No. SHC2639J CTPL 04.04.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SLB2429G
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$995.80
 - (b) Labour Charges \$580.00
 - Total for Part-By-Part Repair Cost** \$1,575.80
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____
3. Estimated normal period for repairs: 2 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : _____
Name : LIM KWOK ENG
Tel : 62148316
Fax : 65468156
Signature : _____
Name : _____
Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305392160
 REGN NO : SHC2639J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 06.09.2018
 DATE/TIME IN : 04.04.2020 10:15
 ACCIDENT DATE : 04.04.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52	de ✓
0002	04-01-0104-2531-G	IONIQVC BRACKET ASSY-RR B	1 L	55.80	20.00	44.64	?
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	de ✓
0004	04-01-0104-2544-G	IONIQVC CAP-RR HOOK	1 L	94.60	20.00	75.68	cut ✓
0005	04-01-0104-2533-G	IONIQV2 MOULDING ASSY-RR	1 L	451.25	20.00	361.00	Cur ✓
0006	04-01-0104-2545-G	IONIQVC MOULDING-REAR BUM	1 L	155.00	20.00	124.00	de ✓
0007	04-01-0104-2288-G	IONIQ BEAM-RR BUMPER	1 L	294.80	20.00	235.84	×
0008	04-01-0104-3819-G	IONIQ STAY-RR BUMPER LH	1 L	138.10	20.00	110.48	?
0009	04-01-0104-3919-G	IONIQ STAY-RR BUMPER RH	1 L	138.10	20.00	110.48	×
0010	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70	10.00	122.13	
0011	04-01-0104-2579-G	IONIQVC GUARD ASSY-REAR W	1 L	73.60	20.00	58.88	?
0012	04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1 N	50.00		50.00	re ✓

SUB-TOTAL : 1,678.25

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 06.04.2020

Time: 12:13:00

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305392160
REGN NO : SHC2639J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 06.09.2018
DATE/TIME IN : 04.04.2020 10:1
ACCIDENT DATE : 04.04.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

00 L PANEL BEATING (repair rr fender Lh)
0001 23-502 SPRAYPAINT ON AFFECTED AREA
0002 17-01 CHECK ALL LIGHTING
0003 20-00 TUFF COAT ON AFFECTED PARTS.
0004 20-22 REMOVE/REFIX REVERSE SENSOR

500.00 320

450.00 200

50.00 30

50.00 X

80.00 30

SUB-TOTAL : 1,130.00

TOTAL : 2,808.25

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Taufik 97495719/67418134
WP

6/4/20 @ 4pm

02 days P/P
Reserving before paint
surc@khawt.com
taufik@khawt.com.

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 23.04.2020

Time: 14:42:32

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305392160
 REGN NO : SHC2639J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 06.09.2018
 DATE/TIME IN : 04.04.2020 10:15
 ACCIDENT DATE : 04.04.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60
0003	04-01-0104-2544-G	IONIQVC CAP-RR HOOK	1 L	94.60	20.00	75.68
0004	04-01-0104-2533-G	IONIQV2 MOULDING ASSY-RR	1 L	451.25	20.00	361.00
0005	04-01-0104-2545-G	IONIQVC MOULDING-REAR BUM	1 L	155.00	20.00	124.00
0006	04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1 N	50.00	2.00-	50.00

SUB-TOTAL : 995.80

JOB NATURE

0000 L	PANEL BEATING (repair rr fender Lh)	320.00
0001 23-502	SPRAYPAINT ON AFFECTED AREA	200.00
0002 17-01	CHECK ALL LIGHTING	30.00
0003 20-22	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 580.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 07.04.2020

Time: 16:50:45

REPAIR ESTIMATE

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305392160
REGN NO : SHC2639J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 06.09.2018
DATE/TIME IN : 04.04.2020 10:1
ACCIDENT DATE : 04.04.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,575.80

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :