

REPAIR ESTIMATE NTUC - LKS
LKK - Ram

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305392007
REGN NO : SHA8277R
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.08.2016
DATE/TIME IN : 03.04.2020 16:00
ACCIDENT DATE : 03.04.2020

JOB PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2322-A	FRT BUMPER	1	1,052.20	20.00	841.76	Rp
0002	04-01-0103-0637-G	FRT BUMPER UPR BRKT LH	1	22.40	20.00	17.92	X nn
0003	04-01-0103-0639-G	FRT BUMPER BRKT LH	1	24.60	20.00	19.68	X nn
0004	04-01-0103-0574-A	FRT FENDER LH	1	663.00	20.00	530.40	bt
0005	04-01-0103-0658-G	FRT WHEEL CAP LH	1	107.10	20.00	85.68	cut
						770.10	
						25% - 616.08	
						SUB-TOTAL	: 1,495.44

JOB NATURE

0000	PB	PANEL BEATING		300.00		280	
0001	SP	SPRAYPAINT-BONNET Etc		750.00		400	
0002	20-00	TUFF COAT ON AFFECTED PARTS.		40.00		30	
0003	20-05	Frt Bumper Adv.Sticker.		100.00		nei	
0004	20-05	Frt Fender Adv.Sticker LH		100.00		nei 910	
						SUB-TOTAL	: 1,290.00

Parts - 616.08
Labour - 910
Supp - 129.60

1655.68
1/5 \$1300
3 days.

NTUC-LIS
LXX-Ram

(SAT)
Date: 04.04.2020
Time: 10:02:42
Page: 2/2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 305392007
REGN NO : SHH8277R
MILEAGE : 000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 25.08.2016
DATE/TIME IN : 03.04.2020 16:0
ACCIDENT DATE : 03.04.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 2,785.44

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749
'WP'
6/4/20 @ 4pm
Luqman
Resurvey after repair
03 days
sur@lkkauto.com
taufik@lkkauto.com