

4/7/2020

<https://vacweb.smrt.com.sg/Estimation.aspx>

Case Details

Case Reference Number :

TAXI 212222

Type of Repair : Accident Repair

Vehicle Registration Number : 5HB132Y

Company Type : SMRT Taxi Pte Ltd

Estimation ID : EST-11103-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 02/04/2020 12 30 PM

Vehicle Age(In Months) : 29

Documents / Photographs

View Documents / Photographs

Total Documents : 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	SMRT Recommendation						Repair/ Replace	Surveyor Approval			Remarks
				Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	0	Repair ☒ R	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ☒ Nec	
One Time Key In	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	1	0	Repair ☒ R	
One Time Key In	Main			WHEEL, DISC R/RH	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	0	Repair ☒ R	
Total Spare Part Cost									2,222.84	Surveyor Total				
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				
Final Spare Part Cost									2,222.84	Final Sur Total				

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH REAR PORTION	507.00	200	
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
Total:			936.00	450.00	

4/7/2020

<https://vacswob.smrt.com.sg/Estimation.aspx>

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
2	Main	TO RESPRAY REAR FENDER RH	378.00	200	
3	Main	TO RESPRAY RIM	180.00	60	
Total:			938.00	450.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
3	Main	TO REPLACE SUNDRY PARTS	100.00	0	
4	Main	TO WASH AND VACUUM	60.00	0	
Total:			380.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,222.84	120.00
Total Labour Cost	507.00	200.00
Total Spray Painting	936.00	450.00
Other	380.00	0.00
Overall Total	4,045.84	770.00
Lump Sum Repair Option		☐
Lump Sum Total	0.00	770.00
Surveyor Approved Amount		770.00
No of Repair Days*	4	2 <i>2 days.</i>
Remarks		P/P, Take before paint photo.
Surveyor Name		Sun Pin (LKK)
Signature		
		Save Clear

4/7/2020

<https://vacswb.smrt.com.sg/Estimation.aspx>

Estimator Assessment(S)

Surveyor Assessment(S)

Survey Date

07/04/2020

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: