

ASS. REC. BY:

REF:

A/G / 2000 50741kk9392

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

1-B.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMA 7706S

Yr Regn:

06, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

S. Wagon

Make:

Honda Shuttle

c.c

1496

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

128310

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP7

1210391

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

R/Bal.

P

mm

Rear

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

mm

D.O.A.

5/4/20

D.O.I.

7/4/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/5

81994.68 Confirmed

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

CLOSE: 29/6/2020



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMA 7706 S

Parts	(a) Cost / List Price Items	\$	2,760.90
	Plus/Less 20%	\$	552.18
	Total of Cost / List	\$	2,208.72
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	2,408.72
Labour		\$	1,590.00
Total		\$	3,998.72

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Name of Surveyor : Kenneth

Company : LKK

Survey conducted on : 7/14/20 at 3.10pm

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor : Lc Date: 7/14/20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SMA 7706 S**
Make & Model : **HONDA SHUTTLE**
Chassis No : **GP71210391**

Submit By : **Serence**
Year Manufacture : **2018**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper	1	\$1,150.60		✓
2	Rear bumper clip	10	\$35.00		✓
3	Rear bumper side retainer LH	1	\$26.50		X
4	Rear bumper side retainer RH	1	\$26.50		✓
5	Rear bumper bracket LH	1	\$48.70		X
6	Rear bumper bracket RH	1	\$48.70		X
7	Rear bumper sponge	2	\$179.00		X
8	Rear bumper reflector RH	1	\$45.00		X
9	Rear bumper reflector garnish RH	1	\$45.00		X
10	RH rear fender	1	\$1,010.90		X
11	RH rear fender undershield	1	\$105.00		✓
12	RH rear fender undershield clip	10	\$40.00		X
13	Reverse sensor	1	\$200.00	s.n	X
14	RH front door	1	757.30		
15	RH front door hinge top	1	48.00		
16	RH front door hinge bottom	1	48.60		
17	RH front door weatherstrip	1	83.30		
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

