



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SMA 7706 S

*Not Authorized
Resurvey B4 paint*

Parts	(a) Cost / List Price Items	\$	2,760.90
	Plus/Less 20%	\$	552.18
	Total of Cost / List	\$	2,208.72
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	200.00
Total Parts Cost		\$	2,408.72
Labour		\$	1,590.00
Total		\$	3,998.72

The above total will be subjected to 7% G.S.T.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 7/4/20 at 3.10pm

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor : Lc Date: 7/4/20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : SMA 7706 S
Make & Model : HONDA SHUTTLE
Chassis No : GP71210391

Submit By : Serence
Year Manufacture : 2018
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear bumper	1	\$1,150.60		✓
2	Rear bumper clip	10	\$35.00		✓
3	Rear bumper side retainer LH	1	\$26.50		X
4	Rear bumper side retainer RH	1	\$26.50		✓
5	Rear bumper bracket LH	1	\$48.70		X
6	Rear bumper bracket RH	1	\$48.70		X
7	Rear bumper sponge	2	\$179.00		X
8	Rear bumper reflector RH	1	\$45.00		X
9	Rear bumper reflector garnish RH	1	\$45.00		X
10	RH rear fender	1	\$1,010.90		X
11	RH rear fender undershield	1	\$105.00		✓
12	RH rear fender undershield clip	10	\$40.00		X
13	Reverse sensor	1	\$200.00	s.n	X
14	RH front door	1	757.30		
15	RH front door hinge top	1	48.60		
16	RH front door hinge bottom	1	48.60		
17	RH front door weatherstrip	1	83.30		
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

