

Not Withheld
 1/10/20
 Resurvey After paint
 6 days

SKQ5601M			6 th APRIL 2020	
1	1 pc	Rear Bumper	BT/UM	\$ 470.39
2	1 pc	Rear Bumper holder - left	D.T	\$ 41.65
3	1 pc	Rear Bumper holder - right	D.T	\$ 41.65
4	2 pc	Rear Bumper Bracket	NISA	\$ 48.44 \$ 96.88
5	10 pcs	Rear bumper clips	M	\$ 3.60 \$ 36.00
6	1 set	Reverse Sensor	NETT	\$ 280.00
7	1 pc	Rear Boot Cover	R	\$ 1,209.65
8	1 pc	Rear Boot rubber	WT	\$ 303.79
9	1 pc	Rear Boot Cover lock - upper	Nd	\$ 443.50
10	1 pc	Rear Boot Cover lock - lower		\$ R 34.86
11	1 pc	Rear End Panel	R	\$ 440.85
12	1 pc	Rear End Panel Garnish	R	\$ 232.96
13	1 pc	Rear Silencer	R	\$ 826.55
14	1 set (3)	Rear Winscreen rubber	M	\$ 60.00 \$ 180.00
15	1 pc	"ELEGANCE" badge	M	\$ 55.00
16	1 pc	"VALVE MATIC" badge	M	\$ 88.00
17		Panel Beating, jack and straighten rear spare tyre compartment, replace , or repair & weld necessary parts		\$ 1,200.00
18		Paint replacement parts and repaint damaged sections with welded portions in and outside		\$ 1,200.00
19		Dismantle N refix rear w/screen glass		\$ 220.00
20		To dismantle and refit rear boot lid accessories , wiper motor check and test electrical circuit		\$ 150.00
Final amount				\$ 7,551.73

✓
 ✓
 ✓
 ✓
 200in
 ✓
 500in
 ✓
 X
 ✓
 ✓
 X
 ✓
 800l
 800l
 120l
 80l

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: