



CLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
KOH WEI SHIONG (XU WEIXIONG)	Cust No/Name /KOH WEI SHIONG (XU WEIXIONG)
BLK 674A JURONG WEST ST 65	Reg No/Reg Date SME5867C*ECB / 08/10/201
#04-64	Date In/Mileage / 0
SINGAPORE 641674	Chassis No KNAF3416MK5011312
Contact No Mobile: 97454226	Engine No G4FGJH702604
	Make/Model KIA/CERATO 1.6 A SR SX G335
	Colour/Trim BBL HORIZON BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	07/04/2020/ 10:20	QUE	261 / Edwin Caina	14527			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000				RENEW FRT BUMPER , FRT FENDER LH & FRT SUPPORT PNL				1100 2750.00
E PNT98000				RESPRAY FRT BUMPER , BONNET & FRT FENDER LH				840 1260.00
E PNT88000				REMOVE & REFIT AIRCON CONDENSER & RADIATOR				NN X 100.00
M SUNDRY				TOP UP AIRCON GAS				NN X 80.00
A 54900099				CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM				50.00
A 10028901				TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				200.00
				USING HI-SCAN PRO TEST				
M SUNDRY				APPLY ANTI CORROSION ON AFFECTED AREAS				40 80.00
M SUNDRY				SUPPLY BODY PNL SEALANT				40 80.00
M SUNDRY				APPLY BODY PAINT PROTECTION <i>Convoite (side of front)</i>				100? 500.00
M SUNDRY				Sundries				20 50.00
M LAMP ASSY-HEAD, LH					1.00	2210.00	00.00	2210.00
M PANEL-FENDER, LH					1.00	430.00	00.00	430.00
M GUARD ASSY-FRONT WHEEL, LH					1.00	95.00	00.00	95.00
M COVER-FR BUMPER					1.00	633.00	00.00	633.00
M GRILLE-FRONT BUMPER					4.00	485.00	00.00	1940.00
M MOULDING-FRONT BUMPER, LH					1.00	43.00	00.00	43.00
M LAMP ASSY-SIDE REPEATER, LH					1.00	143.00	00.00	143.00
M AIR DUCT-FR BUMPER, LH					1.00	14.00	00.00	14.00
M BRACKET-FR BUMPER UPR SIDE MTG					1.00	22.00	00.00	22.00
M ORNAMENT-KIA NO.115					1.00	32.00	00.00	32.00
M CARRIER ASSY-FRONT END MODULE					1.00	675.00	00.00	675.00
M GRILLE ASSY-RADIATOR					1.00	328.00	00.00	328.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
KOH WEI SHIONG (XU WEIXIONG)	Cust No/Name / KOH WEI SHIONG (XU WEIXIONG)
BLK 674A JURONG WEST ST 65	Reg No/Reg Date SME5867C*ECB / 08/10/201
#04-64	Date In/Mileage / 0
SINGAPORE 641674	Chassis No KNAF3416MK5011312
Contact No Mobile: 97454226	Engine No G4FGJH702604
	Make/Model KIA/CERATO 1.6 A SR SX G335
	Colour/Trim BBL HORIZON BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	07/04/2020/ 10:20	QUE	261 / Edwin Caina	14527

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M COOLANT (4L)	1.00	26.00	00.00	NN X 26.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Ram - Hf 90020068

SURVEYOR SIGNATURE: [Signature]

DATE: 10/06/2020 @ 1120

REMARKS: 4 days

Resurvey before paint

Confirm & accepted by

	Nett	11,741.00
7% GST on	11741.00	821.87
Total Payable		12,562.87

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.