



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

UNITED OVERSEAS INSURANCE LTD

Ref : CS/UOI20005086/Gyf3e2

3 ANSON ROAD #28-01
SPRINGLEAF TOWER SINGAPORE 079909

Date : 19-05-2020



Code : UOI2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	GBJ 3817P
Policy No.	DHOM110167731901	Coverage (\$)	0.00
Claim No.	M11D10102004	Excess (\$)	500.00
Assign From	JOSEPHINE WONG	Assign Date	08/04/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA 150	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTFAT35YX0K212539	Colour	BLUE
Odometer	-	Steering	JAMMED
Brakes	JAMMED	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/75 R15	BRIDGESTONE	5 mm
L/H Front Tyre	195/75 R15	BRIDGESTONE	5 mm
R/H Rear Tyre	155 R12	BRIDGESTONE	5 mm
L/H Rear Tyre	155 R12	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/04/2020	Inspection Date	08/04/2020
Survey held at	1 DEFU LANE 6		
Repairer	TAN LIM MOTOR PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$58,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------