


Policy No : DHOM110167731901
Date of Accident : 06 April 2020



TAN LIM MOTOR PTE LTD
1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Claims Department
United Overseas Insurance Ltd
3 Anson Road #28-01
Springleaf Tower
Singapore 079909

Date : 14 April 2020

Supplementary To Repair GBJ3817P - Toyota DYNA 100 MANUAL
Chassis No : JTFAT35YX0K212539

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	n/s front door ✓ BT	\$ 1,600.00
02	1 pc	speedo meter cover ✓ CUT	\$ 168.20
03	1 pc	aircon switch ✓ CRA	\$ 83.10
04	1 pc	gear lever cover ✓ DE	\$ 108.20
05	1 pc	brake pedal bracket ✓ BT	\$ 181.30
06	1 pc	roof top lining ✓ CRUMP	\$ 78.30
			\$ 2,219.10
		Less 25 %	\$ 554.78
			\$ 1,664.33
		<u>LABOUR & MISC. CHARGES</u>	
01		To upholstery and make good repair to cushion seat and seat frame and reclining mechanism. ✓	\$ 120.00
			\$ 120.00
		Total	\$ 1,784.33
		Guo Qiang	
		LKK	

80