

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 9-Apr-20

INSURANCE: MSIG

MODEL: HYUNDAI I40

VEHICLE NO.: SH8061D


DESCRIPTION	QTY	LIST PRICE	AMOUNT
BOOTLID Bst / Dashed	1	\$2,174.90	\$2,174.90
BOOTLID RUBBER <i>distorted</i>	1	\$96.50	\$96.50
BOOTLID HINGE (LH/RH) <i>NH</i>	2	\$284.60	\$569.20
BOOTLID LOCK UPPER <i>SVC</i>	1	\$114.90	\$114.90
BOOTLID LOCK LOWER <i>SVC</i>	1	\$23.20	\$23.20
BOOTLID I40 EMBLEM (I40) <i>Distorted NH</i>	1	\$67.90	\$67.90
BOOTLID 'H' EMBLEM <i>Nec</i>	1	\$63.10	\$63.10
BOOTLID CRDI PLATE <i>Nec NH</i>	1	\$52.40	\$52.40
BOOTLID LAMP (LH/RH) <i>Crack / money crack</i>	2	\$1,131.20	\$2,262.40
BOOTLID TRIMBOARD <i>SVC</i>	1	\$343.90	\$343.90
BOOTLID TRIMBOARD CLIPS (11 PCS) <i>NH</i>	1	\$11.00	\$11.00
BOOTLID MOULDING (I40) <i>NH</i>	1	\$385.30	\$385.30
BOOTLID LOWER GARNISH CHROME(I40) <i>NH</i>	1	\$227.90	\$227.90
REAR BUMPER <i>Distorted</i> <b>553.00</b>	1	\$1,406.00	\$1,406.00
REAR BUMPER REINFORCEMENT BRACKET <i>Bst / Dashed</i>	2	\$160.60	\$160.60
REAR BUMPER REINFORCEMENT <i>Crack</i>	1	\$428.40	\$428.40
REAR BUMPER CLIP <i>Nec</i>	1	\$19.00	\$19.00
REAR BUMPER SPONGE <i>turn</i>	1	\$119.50	\$119.50
REAR BUMPER UNDER COVER <i>distorted</i>	1	\$228.00	\$228.00
REAR BUMPER RUBBER MAT / I40 PLATE <i>Nec</i>	1	\$50.00	\$50.00
REAR BUMPER REFLECTOR LAMP (I40) <i>NH</i>	2	\$32.00	\$64.00
TAIL LAMP (LH/RH) <i>money crack</i>	2	\$697.80	\$1,395.60
TAIL LAMP QUARTER PANEL (LH/RH) <i>NH</i>	2	\$453.00	\$906.00
REAR PANEL <i>Buc</i>	1	\$526.70	\$526.70
REAR PANEL LOWER <i>Buc</i>	1	\$367.20	\$367.20
REAR PANEL GARNISH <i>SVC</i>	1	\$57.70	\$57.70
PANEL ASSY-REAR FLOOR SIDE (LH/RH) <i>NH</i>	2	\$177.00	\$354.00
SPARE TYRE HOLDER <i>NH</i>	1	\$223.10	\$223.10
SPARE WHEEL LOCK NUT <i>NH</i>	1	\$41.80	\$41.80
SPARE TYRE PANEL <i>Distorted</i>	1	\$852.80	\$852.80
SPARE TYRE PANEL CUSHION <i>NH</i>	1	\$223.10	\$223.10
MEMBER-ASSY-REAR FLOOR CENTRE <i>NH</i>	1	\$570.40	\$570.40
REAR TOWING HOOK <i>NH</i>	1	\$194.60	\$194.60
REAR FENDER <i>H/S Distorted</i>	1	\$2,171.40	\$2,171.40
REAR FENDER UNDER SHIELD(LH/RH) <i>NH</i>	1	\$338.60	\$338.60
REAR TRAY LUGGS SIDE (LH/RH) <i>NH</i>	1	\$232.60	\$232.60
REAR FENDER AIR-DUCT (LH/RH) <i>NH</i>	1	\$51.60	\$51.60
REAR FENDER TRIM BOARD (LH/RH) <i>NH</i>	1	\$688.75	\$688.75
EXHAUST PIPE INSULATOR (LH/RH) <i>NH</i>	2	\$117.10	\$234.20
EXHAUST SILENCER (LH/RH) <i>Distorted</i> <b>photo</b>	2	\$1,935.40	\$3,870.80
EXHAUST PIPE HANGER <i>NH</i>	1	\$117.10	\$117.10
<b>SUB TOTAL</b>			<b>\$21,986.15</b>



LESS 20%	12223.30			\$4,397.23
DISCOUNTED TOTAL	9778.64			\$17,588.92
BOOTLID COMFORT LOGO & TEL NO. STICKER <del>ST</del> <sup>Nec</sup> SN	1	\$16.60	\$16.60	✓
BOOTLID ADVERTISEMENT LOGO <del>huc</del> <sup>Nec</sup> SN	1	\$100.00	\$100.00	✓
REAR NO. PLATE <sup>NH</sup> SN	1	\$25.00	\$25.00	X
REAR BUMPER RESERVE SENSOR <sup>Dmc</sup> SN	1	\$118.00	\$118.00	✓
REAR BUMPER ADVERTISEMENT LOGO <del>huc</del> <sup>Nec</sup> SN	1	\$50.00	\$50.00	✓
REAR FENDER ADVERTISEMENT LOGO (LH/RH) <del>huc</del> <sup>Nec</sup> SN	1	\$100.00	\$100.00	✓
SUB TOTAL	434.60			\$409.60
<b>Labour Charge</b>				
Panel Beating	1	\$1,600.00	\$1,600.00	800/-
Spray Painting Charge	1	\$1,200.00	\$1,200.00	700/-
Wiring Charge	1	\$100.00	\$100.00	30/-
Tuff Kote	1	\$120.00	\$120.00	40/-
Towing Charge	1	\$80.00	\$80.00	NH
Remove/Refix Reverse Sensor 1670.00	1	\$120.00	\$120.00	40/-
Remove/Refix Fuel Tank	1	\$80.00	\$80.00	NH
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00	60/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	NH
TOTAL LABOUR				\$3,930.00
ESTIMATE TOTAL				\$ 21,928.52
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

09/04/2020 @ 0915h  
 Hra Ardu  
 2/Share 6 days.

11883.24  
 L/s 9500/-

  
 Hra

LKK Ardu



**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: