



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 35947

LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWER
SINGAPORE 189702

DATE : 07/04/2020
CLAIM NO. : 11539
POLICY NO. : 5108520971

LONPAC INSURANCE BHD

FROM : HASRIANAH

VEHICLE NO. : FBP4375J
MAKE/MODEL : YAM / AEROX

Not Allowed
2u
p/p \$1357.20
3 days.
take photo before
8/4/20

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	AXLE, WHEEL	REPLACE	1.00	\$10.00	304 10.00 ✓
2	BEARING FRONT WHEEL P/N: 52315	REPLACE	2.00	\$13.00	26 26.00 ✓
3	BEARING, STEERING LOWER P/N: 62412	REPLACE	1.00	\$13.00	13 13.00 ✓
4	BEARING, STEERING UPPER P/N: 62411	REPLACE	1.00	\$20.00	20 20.00 ✓
5	BOLT	REPLACE	4.00	\$2.00	8 8.00 ✓
6	BRACKET	REPLACE	1.00	\$5.00	5 5.00 ✓
7	BRACKET	REPLACE	1.00	\$17.00	17 17.00 ✓
8	CALIPER BRAKE FRONT RH	REPLACE	1.00	\$89.00	89 89.00 ✓
9	COVER BODY	REPLACE	1.00	\$26.00	26 26.00 ✓
10	COVER BODY DELTA BOX	REPLACE	1.00	\$26.00	26 26.00 ✓
11	COVER COWLING RH (RED) P/N: 63940	REPLACE	1.00	\$37.00	37 37.00 ✓
12	COVER INNER FRONT MUDGARD	REPLACE	1.00	\$26.00	26 26.00 ✓
13	COVER, FRONT	REPLACE	1.00	\$26.00	26 26.00 ✓

*35947 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	COWLING FRONT	REPLACE	1.00	\$38.00	38.00 ✓
15	DECAL COWLING RH LOWER P/N: 63939	REPLACE	1.00	\$10.00	10.00 ✓
16	DECAL COWLING RH UPPER P/N: 63938	REPLACE	1.00	\$10.00	10.00 ✓
17	DECAL YAMAHA LOGO P/N: 63934	REPLACE	2.00	\$7.00	14.00 ✓
18	FORK FRONT ASSY (alignment)	REPLACE	1.00	\$476.00	476.00 X
19	HEADLAMP ASSY	REPLACE	1.00	\$366.00	366.00 ✓
20	LABOUR P/N: 06766	REPLACE	14.00	\$69.00	966.00 ✓
21	MUDGUARD FRONT	REPLACE	1.00	\$41.00	41.00 ✓
22	MUDGUARD FRONT INNER	REPLACE	1.00	\$14.00	14.00 ✓
23	NUT, SPRING	REPLACE	4.00	\$2.00	8.00 ✓
24	OIL BRAKE (KUTTEN KEULER) DOT 4 P/N: 39338	REPLACE	1.00	\$23.00	23.00 X
25	PLATE DISC BRAKE FRONT P/N: 58182	REPLACE	1.00	\$80.00	80.00 X
26	RETAINER BALL BEARING P/N: 57083	REPLACE	1.00	\$17.00	17.00 ✓
27	RIM FRONT ASSY(GOLD)	REPLACE	1.00	\$254.00	254.00 ✓
28	SEAL DUST	REPLACE	1.00	\$2.00	2.00 ✓
29	SEAL OIL P/N: 61482	REPLACE	2.00	\$2.00	4.00 ✓
30	STICKER 'ABS'	REPLACE	2.00	\$2.00	4.00 ✓
31	STEERING CONE CENTRE P/N: 57078	REPLACE	1.00	\$13.00	13.00 ✓
32	STEERING CONE LOWER P/N: 57080	REPLACE	1.00	\$13.00	13.00 ✓
33	STICKER	REPLACE	1.00	\$11.00	11.00 ✓
34	STICKER	REPLACE	1.00	\$10.00	10.00 ✓
35	STICKER	REPLACE	1.00	\$8.00	8.00 ✓

*35947 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
36	STICKER 3D 'AEROX'	REPLACE	1.00	\$26.00	26.00 <i>17</i> X
37	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	<i>#</i> REPLACE	1.00	\$20.00	20.00 <i>scr</i> ¹⁰
38	STICKER P PLATE P/N: 29128	REPLACE	1.00	\$28.00	28.00 <i>sent</i> ✓
39	TRANSPORT CHARGES P/N: 07169	<i>#</i>	1.00	\$61.00	61.00 <i>35</i>
40	WASHER PLATE P/N: 28656	REPLACE	1.00	\$5.00	5.00 <i>scr</i> ✓
SUB TOTAL					\$2,851.00
GST @ 7 %					\$199.57
GRAND TOTAL					\$3,050.57

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



HASRIANAH

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Paris prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1058
1m
952-20
1357-20

*35947 *

bizSAFE₃





BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 35947

- Rev. 1

LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWER
SINGAPORE 189702

DATE : 07/04/2020
CLAIM NO. : 11539
POLICY NO. : 5108520971

ATTN: MOTOR CLAIMS DEPT

FROM : HASRIANAH

VEHICLE NO. : FBP4375J
MAKE/MODEL : YAM / AEROX

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	ALIGNMENT FRONT FORK	Repair	1.00	\$80.00	80.00
2	AXLE, WHEEL	REPLACE	1.00	\$10.00	9.00
				Disc %: 10.00	
3	BEARING FRONT WHEEL P/N: 52315	REPLACE	2.00	\$13.00	23.40
				Disc %: 10.00	
4	BEARING, STEERING LOWER P/N: 62412	REPLACE	1.00	\$13.00	11.70
				Disc %: 10.00	
5	BEARING, STEERING UPPER P/N: 62411	REPLACE	1.00	\$20.00	18.00
				Disc %: 10.00	
6	BOLT	REPLACE	4.00	\$2.00	7.20
				Disc %: 10.00	
7	BRACKET	REPLACE	1.00	\$5.00	4.50
				Disc %: 10.00	
8	BRACKET	REPLACE	1.00	\$17.00	15.30
				Disc %: 10.00	
9	COVER COWLING RH (RED) P/N: 63940	REPLACE	1.00	\$37.00	33.30
				Disc %: 10.00	
10	COVER INNER FRONT MUDGARD	REPLACE	1.00	\$26.00	23.40
				Disc %: 10.00	
11	COVER, FRONT	REPLACE	1.00	\$26.00	23.40
				Disc %: 10.00	
12	COWLING FRONT	REPLACE	1.00	\$38.00	34.20
				Disc %: 10.00	
13	DECAL COWLING RH LOWER P/N: 63939	REPLACE	1.00	\$10.00	9.00
				Disc %: 10.00	
14	DECAL COWLING RH UPPER P/N: 63938	REPLACE	1.00	\$10.00	9.00
				Disc %: 10.00	

*35947 *

bizSAFE



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-14083
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
15	DECAL YAMAHA LOGO P/N: 63934	REPLACE	2.00	\$7.00	12.60
				Disc %: 10.00	
16	HEADLAMP ASSY	REPLACE	1.00	\$366.00	329.40
				Disc %: 10.00	
17	LABOUR P/N: 06766	REPLACE	1.00	\$280.00	280.00
18	MUDGUARD FRONT	REPLACE	1.00	\$41.00	36.90
				Disc %: 10.00	
19	MUDGUARD FRONT INNER	REPLACE	1.00	\$14.00	12.60
				Disc %: 10.00	
20	NUT , SPRING	Replace	4.00	\$2.00	7.20
				Disc %: 10.00	
21	RETAINER BALL BEARING P/N: 57083	REPLACE	1.00	\$17.00	15.30
				Disc %: 10.00	
22	RIM FRONT ASSY(GOLD)	REPLACE	1.00	\$254.00	228.60
				Disc %: 10.00	
23	SEAL DUST	REPLACE	1.00	\$2.00	1.80
				Disc %: 10.00	
24	SEAL OIL P/N: 61482	REPLACE	2.00	\$2.00	3.60
				Disc %: 10.00	
25	STCIKER 'ABS'	REPLACE	2.00	\$2.00	3.60
				Disc %: 10.00	
26	STEERING CONE CENTRE P/N: 57078	REPLACE	1.00	\$13.00	11.70
				Disc %: 10.00	
27	STEERING CONE LOWER P/N: 57080	REPLACE	1.00	\$13.00	11.70
				Disc %: 10.00	
28	STICKER	REPLACE	1.00	\$11.00	9.90
				Disc %: 10.00	
29	STICKER	REPLACE	1.00	\$10.00	9.00
				Disc %: 10.00	
30	STICKER	REPLACE	1.00	\$8.00	7.20
				Disc %: 10.00	
31	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$10.00	10.00
32	STICKER P PLATE P/N: 29128	REPLACE	1.00	\$28.00	25.20
				Disc %: 10.00	
33	TRANSPORT CHARGES P/N: 07169		1.00	\$35.00	35.00
34	WASHER PLATE P/N: 28656	REPLACE	1.00	\$5.00	4.50
				Disc %: 10.00	

SUB TOTAL

GST @ 7 %

GRAND TOTAL (SGD)

\$1,357.20

\$95.00

\$1,452.20

*35947 *

bizSAFE₃

Address: No. 6, Delu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0303
ISO 9001: 2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	50% deposit required before ordering of parts.				

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*35947 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-140363
ISO 1001:2015