

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

**TAX INVOICE**

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSE  
SINGAPORE 189556

INV No. NA2002736  
INV Date 24/04/2020  
Reference NS/INC20005101/Ftf3n2  
Code INC4

**PROFESSIONAL SERVICE FEE**

Vehicle No. SHC 2291C  
Insured Veh. GBJ 6632K  
Claim No. MT/1090997-002  
Policy No.  
Accident Date 06/04/2020  
Inspection Date 08/04/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>160.00</b>
<b>GST (7%)</b>	<b>11.20</b>
<b>Grand Total</b>	<b>171.20</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'National Assessment Centre Services'**

**National Assessment Centre Services**

*HYN*




## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20005101/Ftf3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 24-04-2020	
			Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBJ 6632K	Veh. Inspected	SHC 2291C	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1090997-002	Excess (\$)	0.00	
Assign From		Assign Date	08/04/2020	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HYUNDAI IONIQ (G3)	c.c	1580	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHC851CVLU186814	Colour	BLUE	
Odometer	74007	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	7 mm	
L/H Front Tyre	195/65 R15	MICHELIN	7 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	8 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	8 mm	
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
Accident Date	06/04/2020	Inspection Date	08/04/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR: <b>2 Working Days</b>			

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2291C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER COVER	DEFORMED / CRACKED	418.30	418.30
1	FRONT BUMPER BRACKET-RH	NOT NECESSARY	28.00	-
1	FRONT BUMPER TOP BRACKET-RH	NOT NECESSARY	12.00	-
10	FRONT BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	FRONT BUMPER GRILLE-RH	SCRATCHED	186.90	186.90
1	FRONT FENDER-RH	NOT NECESSARY	490.70	-
1	FRONT FENDER EMBLEM-BLUE DRIVE	NOT NECESSARY	26.60	-
1	HEADLAMP-RH	SCRATCHED / CRACKED	1,993.65	1,993.65
1	HEADLAMP SUPPORT PANEL	NOT NECESSARY	949.30	-
	LESS 20% DISCOUNT		-825.49	-524.17
			3,301.96	2,096.68
	<b><u>LABOUR</u></b>			
	PANEL BEATING.		700.00	320.00
	SPRAY PAINTING CHARGE.		500.00	200.00
	WIRING CHARGE.		80.00	30.00
	TUFF KOTE.		80.00	30.00
			1,360.00	580.00
	<b>GRAND TOTAL</b>		<b>4,661.96</b>	<b>2,676.68</b>
	<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>2,676.68</b>

Report Ref No. NS/INC20005101/Ftf3n2



PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHC 2291C

INSPECTION







## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H







## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H







## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H







## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H







## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHC 2291C

RE-INSPECTION

