

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBF238B200405

Estimate**Customer**

Name: AIG Asia Pacific Insurance Pte Ltd

Date: 08-04-20

Address: Motor Claims Department

Vehicle No: GBF238B

78 Shenton Way #07-16

Model/Make: Fiat Doblo Cargo

AIG Building

Singapore 079120

Maxi 1.6 MTJ AMT Glaze

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>side 734.34</i>	\$ 745.00	4
2	Bumper Clips 1 set <i>rel 50.00</i>	\$ 65.00	✓
3	Bumper Reinforcement <i>but 520.92</i>	\$ 752.00	✓
4	Bumper Reflector <i>17</i>	\$ 117.60	X
5	Bumper Reverse Sensor <i>shared</i>	\$ 220.00	SN 200 S.N
6	"Corporate" Advertisement & Artwork <i>rel</i>	\$ 180.00	SN 100 S.N
7	Rear Lh Tailgate <i>dp 2355.50</i>	\$ 2,395.00	✓
8	Tailgate Lock <i>17</i>	\$ 331.00	X
9	Tailgate Weatherstrip <i>17</i>	\$ 344.50	X
10	Tailgate Number Plate Lamp 02 pcs (@ \$51.50) <i>17</i>	\$ 103.00	X
11	Tailgate Number Plate Outer Garnish <i>17</i>	\$ 896.00	X
12	Tailgate "70 KM/H" Sticker <i>rel</i>	\$ 15.00	SN 10 S.N
13	Tailgate "Doblo" Emblem <i>rel 80.50</i>	\$ 118.00	✓
14	Tailgate "Maxi" Emblem <i>rel 62.50</i>	\$ 86.00	✓
15	Tailgate Glass Sealant <i>rel</i>	\$ 80.00	SN 40 S.N
16	Tailgate Number Plate and Base <i>17</i>	\$ 48.00	SN X
17	Rear Rh Tailgate Outer Garnish <i>17</i>	\$ 321.80	X
18	Tailgate "Fiat Logo" Emblem <i>17</i>	\$ 87.80	X
19	Tailgate "Professional" Emblem <i>rel 115.00</i>	\$ 163.50	✓
20	Tailgate "6 PAX" Sticker Rh <i>rel</i>	\$ 15.00	SN 10 S.N
21	Tailgate "90" Emblem <i>rel 60.50</i>	\$ 97.50	✓
22	Tailgate "MultiJet" Emblem <i>rel 102.30</i>	\$ 119.60	✓
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	400
	To putty & spray painting & including touch up paint on accident aff	\$ 900.00	600
	Remove & reinstall Rear W Windscreen Glass to facilitate repairs <i>47</i>	\$ 120.00	✓
	Remove and refix rear W tailgate components & wiper mechanism <i>47</i>	\$ 80.00	50
	To check all wiring & electrical component for proper function	\$ 50.00	20
	Remove and refix rear reverse sensor	\$ 100.00	50
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	30

Total Parts & Labour of estimate for damaged vehicle

\$ 9,431.30

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



M/s Liu's Brother Auto Engrg Wks

P. 4081-53

10%

P-3673-40

S.N-360-00

A-1270-00

563-40

202

4/11/20

Not Authorised

new

9/4/20

4/5 4200

Take photo of the damage

4 days.