



FALCON-AIR

RADHA EXPORTS PTE LTD
40 PANDAN ROAD SINGAPORE
609282

Attention : Motor Claim Department
Contact : 6220 2777 90022731

Page 1 / 2
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003639

Date : 06/04/2020
Vehicle Num. : SJD6787J
Make/Model : MIT LANCER EX 1.5-28/FEB 2023
Chassis/Eng# : JMYSRCY2A8U004502
Accident Date : 03/04/2020
Claim No. :
Reference : TP NTUC VS MSFCI
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	BOOTLID LOGO <i>new</i>		47.00
2.	1	BOOTLID EMBLEM LANCER <i>new</i>		52.00
3.	1	BOOTLID EMBLEM EX <i>new</i>		39.00
4.	1	BOOTLID EMBLEM MIVEC <i>new</i>		41.00
5.	1	BOOTLID SHOCK ABSORBER LH/RH <i>X</i>		92.00
6.	1	REAR BUMPER <i>de</i>		815.00
7.	1	REAR BUMPER SIDE RETAINER RH <i>new</i>		28.00
8.	1	REAR BUMPER REFLECTOR <i>new</i>		30.00
9.	1	REAR BUMPER REINFORCEMENT <i>?</i>		210.00
10.	1	REAR BUMPER BEAM <i>?</i>		102.00
11.	1	REAR END PANEL <i>?</i>		506.00
12.	1	TOW COVER <i>ms</i>		28.00

List Total S\$:	1,990.00
20.00% Discount S\$:	398.00
	<u>1,592.00</u>

SPECIAL NETT ITEMS :				
1.	1	REVERSE SENSOR <i>cut</i>		200.00
Special Nett Total S\$:				<u>200.00</u>

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D**FALCON-AIR**RADHA EXPORTS PTE LTD
40 PANDAN ROAD SINGAPORE
609282

Attention : Motor Claim Department

Contact : 6220 2777 90022731

Estimate : ES003639

Date : 06/04/2020

Vehicle Num. : SJD6787J

Make/Model : MIT LANCER EX 1.5-28/FEB 2023

Chassis/Eng#: JMYSRCY2A8U004502

Accident Date : 03/04/2020

Claim No. :

Reference : TP NTUC VS MSFCI

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :

TO REALIGN EXHAUST PIPE/BOX
 TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING
 TO RUSTPROOF ON ACCIDENT DAMAGE AREAS
 SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER
 TO CUT OUT/REWELD REAR END PANEL, REPAIR BOOTLID
 REAR CHASSIS, SPARE TYRE PANEL, RH REAR FENDER
 INCLUDES KNOCKING & REPLACEMENT OF PARTS

100.00
 120.00
 150.00
 1,100.00

750.00
 600

Labour Total S\$:

2,220.00

Paul
 4p 90010068
 5 days
 45
 27/05/2020 @ 1405
 Resy after repair

SingDollars : Four Thousand Twelve Only

E. & O.E.

Total S\$: 4,012.00

for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel 6452-0880/6458-0880 Fax 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel 6789-7997 Fax 6788-7997 • No 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel 6779-5665 Fax 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg