



FALCON-AIR

RADHA EXPORTS PTE LTD
40 PANDAN ROAD SINGAPORE
609282

Attention : Motor Claim Department
Contact : 6220 2777 90022731

Estimate : ES003639

Date : 06/04/2020
Vehicle Num. : SJD6787J
Make/Model : MIT LANCER EX 1.5-28/FEB 2023
Chassis/Eng# : JMYSRCY2A8U004502
Accident Date : 03/04/2020
Claim No. :
Reference : TP NTUC VS MSFCI
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	BOOTLID LOGO		47.00
2.	1	BOOTLID EMBLEM LANCER		52.00
3.	1	BOOTLID EMBLEM EX		39.00
4.	1	BOOTLID EMBLEM MIVEC		41.00
5.	1	BOOTLID SHOCK ABSORBER LH/RH		92.00
6.	1	REAR BUMPER		815.00
7.	1	REAR BUMPER SIDE RETAINER RH		28.00
8.	1	REAR BUMPER REFLECTOR		30.00
9.	1	REAR BUMPER REINFORCEMENT		210.00
10.	1	REAR BUMPER BEAM		102.00
11.	1	REAR END PANEL		506.00
12.	1	TOW COVER		28.00
List Total S\$:				1,990.00
20.00% Discount S\$:				398.00
				1,592.00
SPECIAL NETT ITEMS :				
1.	1	REVERSE SENSOR		200.00
Special Nett Total S\$:				200.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

RADHA EXPORTS PTE LTD
40 PANDAN ROAD SINGAPORE
609282

Attention : Motor Claim Department

Contact : 6220 2777 90022731

Page 2 / 2
FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES003639

Date : 06/04/2020
Vehicle Num. : SJD6787J
Make/Model : MIT LANCER EX 1.5-28/FEB 2023
Chassis/Eng#: JMYSRCY2A8U004502
Accident Date : 03/04/2020
Claim No. :
Reference : TP NTUC VS MSFCI
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		TO REALIGN EXHAUST PIPE/BOX		100.00
		TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING		120.00
		TO RUSTPROOF ON ACCIDENT DAMAGE AREAS		150.00
		SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER		1,100.00
		TO CUT OUT/REWELD REAR END PANEL, REPAIR BOOTLID		
		REAR CHASSIS, SPARE TYRE PANEL, RH REAR FENDER		
		INCLUDES KNOCKING & REPLACEMENT OF PARTS		750.00
		Labour Total S\$:		2,220.00

SingDollars : Four Thousand Twelve Only

E. & O.E.

Total S\$: 4,012.00

for FALCON AIR AUTO SERVICES PTE LTD



FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

Enquire Transaction History

Transaction History Details

Log Date/Time: 04 Apr 2020 / 11:46:58

Asset Type:	Vehicle	Transaction Amount:	\$7.49
Asset ID:	SHC3328A		
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)	Channel:	External Agency
User ID:	EFAANJ00 - NG JACQUELINE	Business Transaction Reference No.:	20200404114658245089

Search Date / Time: 03 Apr 2020 21:30:00

Insurance Company: MS FIRST CAPITAL INSURANCE LIMITED

Information displayed is correct as at the log date and time.

Enquire Related Logs

OK