



FALCON-AIR

Page 1 / 2

FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

RADHA EXPORTS PTE LTD
40 PANDAN ROAD SINGAPORE
609282

Attention : Motor Claim Department
Contact : 6220 2777 90022731

Estimate : ES003639

Date : 06/04/2020
Vehicle Num. : SJD6787J
Make/Model : MIT LANCER EX 1.5-28/FEB 2023
Chassis/Eng# : JMYSRCY2A8U004502
Accident Date : 03/04/2020
Claim No. :
Reference : TP NTUC VS MSFCI
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	BOOTLID LOGO <i>new</i>		47.00
2.	1	BOOTLID EMBLEM LANCER <i>new</i>		52.00
3.	1	BOOTLID EMBLEM EX <i>new</i>	1796.00	39.00
4.	1	BOOTLID EMBLEM MIVEC <i>new</i>	20%	41.00
5.	1	BOOTLID SHOCKABSORBER LH/RH <i>X NN</i>	1436.80	92.00
6.	1	REAR BUMPER <i>de</i>		815.00
7.	1	REAR BUMPER SIDE RETAINER RH <i>new</i>		28.00
8.	1	REAR BUMPER REFLECTOR <i>new</i>		30.00
9.	1	REAR BUMPER REINFORCEMENT <i>? BT</i>		210.00
10.	1	REAR BUMPER BEAM <i>? X SVC</i>		102.00
11.	1	REAR END PANEL <i>? BT</i>		506.00
12.	1	TOW COVER <i>MS</i>		28.00
List Total S\$:				1,990.00
20.00% Discount S\$:				398.00
				1,592.00
SPECIAL NETT ITEMS :				
1.	1	REVERSE SENSOR <i>cut</i>	S/N 200	200.00
Special Nett Total S\$:				200.00

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D**FALCON-AIR**RADHA EXPORTS PTE LTD
40 PANDAN ROAD SINGAPORE
609282Attention: Motor Claim Department
Contact: 6220 2777 90022731

Estimate: ES003639

Date: 06/04/2020
Vehicle Num.: SJD6787J
Make/Model: MIT LANCER EX 1.5-28/FEB 2023
Chassis/Eng#: JMYSRCY2A8U004502
Accident Date: 03/04/2020
Claim No.:
Reference: TP NTUC VS MSFCI
Policy No.:

S/N Quantity Particular Unit Price Amount S\$

LABOUR:
TO REALIGN EXHAUST PIPE/BOX
TO REMOVE/REPLACE REVERSE SENSOR & CHECK WIRING
TO RUSTPROOF ON ACCIDENT DAMAGE AREAS
SPRAY PAINTING ON ACCIDENT DAMAGED AREAS INNER/OUTER
TO CUT OUT/REWELD REAR END PANEL, REPAIR BOOTLID
REAR CHASSIS, SPARE TYRE PANEL, RH REAR FENDER
INCLUDES KNOCKING & REPLACEMENT OF PARTS

1580

~~100.00~~ 60
~~120.00~~ 60
~~150.00~~ 60
~~1,100.00~~ 800

Labour Total S\$:

1436.80
200.00
1580.00

3216.80

20%

2573.44

L/S \$ 2550.00

5 DAYS

SingDollars: Four Thousand Twelve Only

E. & O.E.

Total S\$: 4,012.00

=====

for FALCON AIR AUTO SERVICES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Websites: www.falconair.com.sg E-mail: email@falconair.com.sg