

# SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

AMV PTE LTD  
c/o 46 Lentor Plain  
Singapore 786548

*Not Authorised*  
*11 by 83050*  
*Resurvey After Paint*  
*4 days*

Date: 26/2/2018

| QUANTITY | PARTICULARS                                                                                                   | AMOUNT (\$)    |
|----------|---------------------------------------------------------------------------------------------------------------|----------------|
|          | <b>RE: MAZDA 3 / SLF406P</b>                                                                                  |                |
| 1 pc     | rear bumper reinforcement <b>537.20</b>                                                                       | BT 583.20 ✓    |
| 1 pc     | rear bumper <b>1074.80</b>                                                                                    | Bu 1,178.50 ✓  |
| 2 pcs    | rear bumper tow cover @ 33.70                                                                                 | nd 67.40 ✓     |
| 2 pcs    | rear bumper reflector @ 127.50                                                                                | ln 255.00 X    |
| 2 pcs    | rear boot hinge @ 197.30                                                                                      | ln 394.60 X    |
| 1 pc     | rear boot lid                                                                                                 | nd/ln 986.30 ✓ |
| 1 pc     | rear boot 'LOGO'                                                                                              | ln 82.60 ✓     |
| 1 pc     | rear boot emblem "MAZDA 3"                                                                                    | ln 63.80 ✓     |
| 1 pc     | rear boot emblem "SKYACTIVE TECHNOLOGY"                                                                       | ln 75.60 ✓     |
| 1 pc     | rear boot lock                                                                                                | ln 291.30 X    |
| 1 pc     | rear boot weatherstrip                                                                                        | ln 326.80 X    |
| 2 pcs    | rear boot lamp @ 296.80                                                                                       | ln 593.60 X    |
| 2 pcs    | rear tail lamp assy <b>568.40</b>                                                                             | ln 1,136.80 ✓  |
| 1 pc     | end panel garnish                                                                                             | ln 328.60 X    |
| 1 pc     | end panel                                                                                                     | ln 369.20 X    |
|          | Sub-total                                                                                                     | 208 6,733.30   |
|          | Less 15%                                                                                                      | 1,010.00       |
|          | Sub-total                                                                                                     | 5,723.31       |
| 1 set    | reverse sensor                                                                                                | shor 200.00 ✓  |
|          | Sub-total                                                                                                     | 5,923.31       |
|          | To remove and replace all the parts mentioned above, knocking and straighten up the necessary affected areas. | 600.00 400     |
|          | To install reversensor.                                                                                       | 100.00 50      |
|          | To apply putty and spray painting on affected areas.                                                          | 800.00 400     |
|          | To apply waterproof sealant on affected areas.                                                                | ln 50.00 X     |
|          | To apply rust proofing on affected areas.                                                                     | 50.00 30       |
|          | Total                                                                                                         | 7,523.31       |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_

s.nett