



新友合汽车私人有限公司 SIN YEW HUP AUTO PTE LTD

393M, Woodlands Road, Yew Tee Industrial Estate, Singapore 677981
Tel: 6760 0819 Fax: 6769 0221 Email: syhapl@singnet.com.sg
Specialise in Insurance Claims and General Motor Repair Work

Co./GST Regn. No. 200921075G

08 Apr 2020

THIRD PARTY CLAIM

Third Party Vehicle No : SHA5170J

Date of Accident : 04/04/2020

Mr Wong Sung Toon

C/o 393M Woodlands Road

Yew Tee Industrial Estate

Singapore 677981

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED COST OF REPAIR TO HYUNDAI ELANTRA : SLS 4451 M

A) Chassis No : KMHD841CMJU543676

B) Date of Registration : 23/09/2017

S/No.	Pc/s	Item(s) :-	\$
01.	1	rear bumper	459.00
02.	1	rear bumper side holder @\$44.30 <i>pp ? RH-</i>	88.60
03.	1	rear bumper reflector @\$41.00 <i>? RH</i>	82.00
04.	1	rear bumper lower garnish <i>SCA</i>	250.00
05.	8	rear bumper clip @\$4.80 <i>Nec</i>	38.40
06.	1	rear bumper reinforcement	294.00
07.	1	rear bumper bracket	28.00

1,240.00

Less 20% discount:-

248.00

992.00

08. 1 Special Nett Item(s) :-
reverse sensor *short*

250.00 *200*

Labour Charges :

a) To dismantle all accident damaged parts, panel beat/straighten, all dents, check, adjust, remove and re-install necessary fittings, replace and re-align the above parts

300.00 *200*

b) To putty and spray paint rear bumper, rear bumper reinforcement and all affected portion

300.00 *200*

1,842.00

GST (7%) :-

128.94

Total :-

1,970.94

=====

Repair day - 3 days.

P/P.

before paint photo.

Sunpin (LKK)

04/04/2020.

TP without prejudice

sy sunpin@lkkauto.com.