



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

FOR

T P CLAIM

FINALIZATION

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 26/06/2020	Mr Ang Kian Kee 87 Zion Road #23-176 Singapore 160087 Mobile: 90107005

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AEXRKT E1	NSP151R	29/01/2018	SLW0631R	0	54789	84/TP/SLW0631R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3X01105010	2NRX253358	60	Joe Tan Joo Seng	22/06/2020	8.00	25/06/2020	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P CLAIM:C/TAIPING ACC DATE:08/04/20 TOW/DRIVE IN:DRIVE DATE-IN:22/06/20 DATE SURVEY:10/06/20 NO OF REPAIR DAYS:05 DAYS BY:LKK-RASUL AUTHORISED ON:24/04/20				50.00
2	B	BP-LAB2 TO CHECKE WIRING, LIGHTINGS AND CARRY OUT WATER LEAK TEST.	*			122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME	18			180.00
4	B	BP-LAB2 TO REMOVE AND TRANSFER REAR BOOT LID COPONENT AND MECHANISM TO NEW BOOT LID.	*			360.00
5	B	BP-LAB2 TO DRILL HOLE AND RE-INSTALL REAR SENSOR	*			180.00
6	Z	BP-SLANT SUPPLY SEALANT (NETT)				60.00
7	B	BP-LAB2 TO REMOVE ALL NECESSARY DAMAGED PARTS, R EPLACE, REPAIR END PANEL. REINFORCEMENT, REAR BUMPER, BOOT LID AND AFFECTED REAR PORTION OF CAR.	*			1440.00
8	B	BP-RES2 TO SPRAY PAINT ON DAMAGED AFFECTED REAR PORTION OF CAR.	*			1770.00
9	1	S52159-0U963 COVER, RR BUMPER L/C	1.00	526.00		526.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4217354

TO SECURITY GUARD

4217354

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 26/06/2020
TIME 08:20

VEHICLE NO

SLW0631R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Ang Kian Kee 87 Zion Road #23-176 Singapore 160087 Mobile: 90107005
	Document No	
	Document Date	
	0	
	26/06/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AEXRKT	E1	NSP151R	29/01/2018	SLW0631R	0	54789 84/TP/SLW0631R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3X01105010	2NRX253358	60	Joe Tan Joo Seng	22/06/2020	8.00	25/06/2020	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	2	S52161-0K040	PIECE, RR BUMPER	10.00	4.10	41.00
11	3	S75895-0D270	TAPE, MOULDING, NO.1	2.00	50.40	100.80
12	4	SPC507-0D015 17	BACK SENSOR 1D4 SILVER METALLI	1.00	193.90	193.90
13	5	S64401-0D360	PANEL, LUGGAGE DR22	1.00	793.20	793.20
14	6	T90975-02063	EMBLEM, LUGGAGE22	1.00	50.70	50.70
15	7	S75442-0D400	PLATE, LUGGAGE22	1.00	45.60	45.60
16	8	S75444-0D690	PLATE, LUGGAGE22	1.00	35.50	35.50

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	
	Please acknowledge receipt of vehicle	Parts	5,949.10	
		Labour	1,786.70	
		Materials	4,162.40	
		Lubrication/Fluid	0.00	
		Others	0.00	
			0.00	
			0.00	
			GST 7.00%	416.44
			Less	0.00
			Amount Due	6,365.54

PLEASE TEAR ALONG PERFORATED LINE

4217355

TO SECURITY GUARD

4217355

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 26/06/2020
TIME 08:20

VEHICLE NO SLW0631R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Vehicle Diagnostic Report

2NRFE
026216 km

MR2B23F3X01105010

Borneo Motors

Printed By: Default User(1)

23/06/2020 2:21:58 PM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed		
Engine and ECT	No	P1605			X		-	30DW12C0 A020200C
SRS Airbag	No	B1821			X		-	8917F0D452
Cruise Control							-	-
ABS/VSC/TRC							-	F152652A30
Steering Angle Sensor							-	8924GF4010
EMPS							-	8965B0D140
Air Conditioner							-	886500D87001
Combination Meter							-	838000UV3002
Entry&Start							-	-
Starting Control							-	-
Power Source Control							-	-

Vehicle Diagnostic Report

2NRFE
026216 km

MR2B23F3X01105010

Borneo Motors

Printed By: Default User(1)

23/06/2020 2:22:47 PM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed		
Engine and ECT							-	30DW1200
							-	A020200C
Cruise Control							-	-
ABS/VSC/TRC							-	F152652A30
Steering Angle Sensor							-	8924GF4010
EMPS							-	8965B0D140
Air Conditioner							-	886500D87001
Combination Meter							-	838000UV3002
Entry&Start							-	-
SRS Airbag							-	8917F0D452
Starting Control							-	-
Power Source Control							-	-