

TOYOTA

: 196700086Z
: MR-8500000-9

T/P CLAIM

ESTIMATE

"My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail		Account No	Customer Detail	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mr Ang Kian Kee 87 Zion Road #23-176 Singapore 160087	
		Document No	Mobile: 90107005	
		Document Date		
		08/04/2020		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AEXRKT E1	NSP151R	29/01/2018	SLW0631R	0	54789	84/TP/SLW0631R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3X01105010	2NRX253358	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P CLAIM: ACC DATE:08/04/20 TOW/DRIVE IN: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00
2	B	BP-LAB2 TO CHECKE WIRING, LIGHTINGS AND CARRY OUT WATER LEAK TEST.				122.40
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
4	L	BP-LPO SUPPLY REAR REGN PLATE (PO#)				180.00
5	B	BP-LAB2 TO REMOVE AND TRANSFER REAR BOOT LID COPONENT AND MECHANISM TO NEW BOOT LID.				360.00
6	B	BP-LAB2 TO DRILL HOLE AND RE-INSTALL REAR SENSOR				180.00
7	Z	BP-SLANT SUPPLY SEALANT (NETT)				60.00
8	B	BP-LAB2 TO REMOVE ALL NECESSARY DAMAGED PARTS, R EPLACE, REPAIR END PANEL. REINFORCEMENT, REAR BUMPER, BOOT LID AND AFFECTED REAR PORTION OF CAR.				1440 3600.00
9	B	BP-RES2 TO SPRAY PAINT ON DAMAGED AFFECTED REAR PORTION OF CAR.				1770 3540.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4219178

TO SECURITY GUARD

4219178

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 08/04/2020
TIME 12:40

VEHICLE NO SLW0631R

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

TOYOTA

: 196700086Z
: MR-8500000-9

ESTIMATE

"My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Account Detail

Account No

Customer Detail

THIRD PARTY CLAIM

S1000020 / TPCLAIM

Document No

0

Document Date

08/04/2020

Mr Ang Kian Kee
87 Zion Road
#23-176
Singapore 160087

Mobile: 90107005

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AEXRKT E1	NSP151R	29/01/2018	SLW0631R	0	54789	84/TP/SLW0631R
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MR2B23F3X01105010	2NRX253358	60	Joe Tan Joo Seng	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	1	S52159-OU963 COVER, RR BUMPER L/C <i>de</i>	1.00	526.00		✓ 526.00
11	2	S52023-OD090 REINFORCEMENT SUB-AS <i>? Xsue</i>	1.00	332.70		332.70
12	3	S52161-OK040 PIECE, RR BUMPER <i>ne</i>	10.00	4.10		✓ 41.00
13	4	S75895-OD270 TAPE, MOULDING, NO. 1 <i>ne</i>	2.00	50.40		✓ 100.80
14	5	S52576-OD330 RETAINER, RR BUMPER <i>? Xsue</i>	1.00	154.80		154.80
15	6	S52575-OD340 RETAINER, RR BUMPER <i>? Xsue</i>	1.00	154.80		154.80
16	7	SPC507-OD015 17 BACK SENSOR 1D4 SILVER METALLI <i>mis</i>	1.00	193.90		✓ 193.90
17	8	T89997-30100 ANTENNA, ELECTRICAL <i>? Xsue</i>	1.00	72.00		72.00
18	9	S52015-OD130 ARM SUB-ASSY, RR BUM <i>? Xsue</i>	2.00	68.70		137.40
19	0	S58307-OD480 PANEL SUB-ASSY, BODY <i>? Xsue</i>	1.00	742.30		742.30
20	1	S64401-OD360 PANEL SUB-ASSY, LUGG <i>ne</i>	1.00	793.20		✓ 793.20
21	2	S64600-OD040 LOCK ASSY, LUGGAGE C <i>Xsue</i>	1.00	399.50		399.50
22	3	T90975-02063 REAR BOOT LID EMBLEM, <i>ne</i>	1.00	50.70		✓ 50.70
23	4	S75442-OD400 PLATE, LUGGAGE COMPT <i>ne</i>	1.00	45.60		✓ 45.60
24	5	S75444-OD690 PLATE, LUGGAGE COMPT <i>ne</i>	1.00	35.50		✓ 35.50
25	6	S81580-OD500 LAMP ASSY, RR, RH <i>? Xsue</i>	1.00	245.80		245.80
26	7	S81590-OD500 LAMP ASSY, RR, LH <i>? Xsue</i>	1.00	245.80		245.80

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of	Customer's Signature	Change Summary	Total
Borneo Motors			12,494.20
LKK Auto Consultants	Please acknowledge receipt of vehicle	Parts 4,271.80	GST 7.00% 874.59
the Repairer of the following:		Labour 8,142.40	Less 0.00
• To resurvey before/after spray painting		Materials 80.00	
• To display damaged part(s) during resurvey		Lubrication/Fluid 0.00	
• Parts prices are subject to confirmation		Others 0.00	
• Third party survey is on a "Without Prejudice" basis			Amount Due 13,368.79
• No illegal modification(s) is allowed			
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

Signature:

DATE

08/04/2020

PLEASE ALLOW THE UNDERMENTIONED

TIME

12:40

VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLW0631R

CUSTOMER

SIGNATURE

FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors