



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CS3/III18011588/Gvf3e2-1

64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Date : 24-04-2020



Code : III2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 1795Y	Veh. Inspected	GBD 1728H
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT18050882	Excess (\$)	0.00
Assign From	DERRICK TAN	Assign Date	07/04/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTFAT35Y00K203171	Colour	SILVER
Odometer	127431	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	MICHELIN	5 mm
L/H Front Tyre	195 R15	MICHELIN	5 mm
R/H Rear Tyre	155 R12	FIRESTONE	5 mm
L/H Rear Tyre	155 R12	FIRESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	30/05/2018	Inspection Date	27/06/2018
Survey held at	TEK SOON MOTOR REPAIR & SPRAY PAINTING AUTOBAY @ KAKI BUKIT 1 KAKI BUKIT AVE 6 BLK D #01-93 SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------