

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 13 Apr 2020

Preliminary Advice

Insured Vehicle No	:	GBG9165M		
TP Vehicle No	:	SMF9412A	Accident Date	: 05/04/2020
Make	:	MAZDA 3	Assignment Date	: 09/04/2020
Date of Inspection	:	09/04/2020	Est. Duration of Repair	: 4.00
Inspection At	:	KUM CHEW MOTOR WORKSHOP (HQ) 12 SIN MING INDUSTRIAL ESTATE, #01-71 SINGAPORE 575656		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 3,959.04
Revised Amount	:	S\$ 2,617.12
Check Items (Estimated)	:	S\$ 229.68
Total	:	S\$ 2,846.80
Lump Sum Repair		: