

ASS. REC. BY:

REF: A/GKenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 09 days

Res.: Yes or No

Lum Sum: 1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: SMR 33547Yr Regn: 01, 20Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or _____

Make: HyundaiA/C: Avante c.c. 1591Colour: M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 14563

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH08410M211010783Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rlm / STD / Rlm or

Tyre Size: F: _____

R: _____

195/85R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Arxen

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 6/4/20D.O.I. 13/4/2020

Survey held at _____

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop orols body

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Date: 09.04.2020
Vehicle No: SMR5354Y
Model: HYUNDAI AVANTE 1.6 GLS
Chassis: KMHD841CMLU010783-2019
Reg.Year: 2020

Third Party Insurer: AIG
Third Party Veh No: GBH371M
Date of Accident: 06.04.2020

Not Authorised
Accident B4 paint 9 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT DOOR RH	1		<i>Rt</i> \$1,467.50	✓
2	FRONT DOOR OUTER HANDLE RH	1		<i>Bro</i> \$121.60	✓
3	FRONT DOOR OUTER HANDLE BASE RH	1		<i>mr</i> \$105.70	✓
4	FRONT DOOR OUTER HANDLE COVER RH	1		<i>mr</i> \$45.00	✓
5	FRONT DOOR CYLINDER KEYLOCK RH	1		<i>mr</i> \$240.00	✓
6	FRONT DOOR INNER TRIM CLIPS RH	10	\$6.50	\$65.00	?
7	FRONT DOOR FRAME PROTECTIVE STICKER RH	1		<i>na</i> \$40.00	✓
8	FRONT DOOR POWER WINDOW GEAR ASSY RH	1		<i>Sm</i> \$1,150.10	x
9	FRONT DOOR WINDOW GLASS RH	1		\$485.50	?
10	FRONT DOOR GLASS OUTER MOULDING RH	1		\$79.50	?
10	REAR DOOR RH	1		<i>Rt</i> \$1,476.80	✓
11	REAR DOOR INNER LOCK RH	1		<i>In</i> \$257.20	✓
12	REAR DOOR OUTER HANDLE RH	1		<i>mgmt</i> \$121.60	✓
13	REAR DOOR OUTER HANDLE INNER BASE RH	1		\$105.70	?
14	REAR DOOR FRAME PROTECTIVE STICKER RH	1		<i>na</i> \$40.00	✓
15	REAR DOOR INNER TRIM CLIPS RH	10	\$6.50	\$65.00	?
16	REAR QUARTER PANEL RH	1		<i>Rt</i> \$1,852.50	✓
17	REAR QUARTER PANEL INNER TRIM COVERING CLIPS	12	\$6.80	<i>na</i> \$81.60	x
18	REAR ALLOY RIM RH	1		<i>Del</i> \$895.20	✓
19	REAR AXLE BEAM ASSY	1		\$2,025.00	?
20	REAR WHEEL BEARING ASSY RH	1		\$402.70	?
21	REAR TAIL LAMP RH	1		<i>Bro</i> \$482.50	✓
22	REAR TAIL LAMP PANEL RH	1		\$338.20	?
23	REAR BUMPER	1		<i>mgmt</i> \$980.00	✓
24	REAR BUMPER SIDE BRACKET RH	1		<i>mr</i> \$58.00	✓
25	REAR FENDER INNER LINER RH	1		\$328.60	?
26	REAR BUMPER CLIPS	8	\$5.80	<i>na</i> \$46.40	✓
27	REAR BUMPER LOWER LAMP RH	1		<i>Sm</i> \$476.00	x
28	REAR BUMPER LOWER LAMP GARNISH	1		<i>Sm</i> \$596.30	✓
29	REAR WINDSCREEN GLASS	1		<i>Shatter</i> \$945.00	✓
30	REAR WINDSCREEN RUBBER	1		<i>na</i> \$120.00	✓
31	REAR BOOT	1		REPAIR	
32	REAR QUARTER PANEL LOWER SILL MEMBER RH	1		REPAIR	
33	RUNNING BOARD PANEL RH	1		REPAIR	
SUB TOTAL				\$15,494.20	
LESS 20%				-\$3,098.84	
PARTS TOTAL				\$12,395.36	

Head office

6 Yung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 09.04.2020
 Vehicle No: SMR5354Y
 Model: HYUNDAI AVANTE 1.6 GLS
 Chassis: KMHD841CMLU010783-2019
 Reg.Year: 2020

Third Party Insurer: AIG
 Third Party Veh No: GBH371M
 Date of Accident: 06.04.2020

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR WINDSCREEN SEALANT	1		\$80.00
2	REAR WINDSCREEN STOPPER	2	\$15.00	\$30.00
3	REAR WINDSCREEN DECAL STICKER	1		\$20.00
			S/N TOTAL	\$130.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, READJUST REAR ACCIDENT AREAS & ETC.

\$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR RH, REAR DOOR RH, REAR QUARTER PANEL RH, REAR BUMPER, REAR BOOT LID, RUNNING BOARD PANEL RH & ETC.

\$1,300.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT & REAR DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

\$240.00

LABOUR CHARGES TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC.

\$80.00

LABOUR CHARGES TO REMOVE, REFIX, REPLACE REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETC.

\$120.00

LABOUR CHARGES TO REMOVE, REPLACE & READJUST REAR ABSORBER, REAR AXLE BEAM ASSY, REAR WHEEL BEARING & ETC.

\$350.00

LABOUR CHARGES TO REMOVE & REPLACE REAR ALLOY RIM RH & ETC.

\$80.00

TO WHEEL ALIGNMENT & BALANCING.

\$80.00

TO DIAGNOSE FAULTY CODE & RESET MEMORY.

\$120.00

LABOUR TOTAL \$3,370.00

TingAn		TOTAL	\$15,895.36
--------	--	-------	-------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

