

Date: 09.04.2020  
 Vehicle No: SMR5354Y  
 Model: HYUNDAI AVANTE 1.6 GLS  
 Chassis: KMHD841CMLU010783-2019  
 Reg.Year: 2020

Third Party Insurer: AIG  
 Third Party Veh No: GBH371M  
 Date of Accident: 06.04.2020

*Not Authorised  
Repair by paint*

9 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT \$	AMOUNT \$
(1)	FRONT DOOR RH	1		R1 \$1,467.50 ✓
(2)	FRONT DOOR OUTER HANDLE RH	1		Bra \$121.60 ✓
(3)	FRONT DOOR OUTER HANDLE BASE RH	1		m1 \$105.70 ✓
(4)	FRONT DOOR OUTER HANDLE COVER RH	1		mry \$45.00 ✓
(5)	FRONT DOOR CYLINDER KEYLOCK RH	1		mry \$240.00 ✓
6	FRONT DOOR INNER TRIM CLIPS RH	10	\$6.50	NN \$65.00 X
(7)	FRONT DOOR FRAME PROTECTIVE STICKER RH	1		ra \$40.00 ✓
8	FRONT DOOR POWER WINDOW GEAR ASSY RH	1		ra \$1,150.10 X
9	FRONT DOOR WINDOW GLASS RH	1		ra \$485.50 X
10	FRONT DOOR GLASS OUTER MOULDING RH	1		ra \$79.50 X
(10)	REAR DOOR RH	1		R1 \$1,476.80 ✓
11	REAR DOOR INNER LOCK RH	1		In \$257.20 ✓
(12)	REAR DOOR OUTER HANDLE RH	1		mry \$121.60 ✓
(13)	REAR DOOR OUTER HANDLE INNER BASE RH	1		ra \$105.70 R ✓
(14)	REAR DOOR FRAME PROTECTIVE STICKER RH	1		ra \$40.00 ✓
15	REAR DOOR INNER TRIM CLIPS RH	10	\$6.50	NN \$65.00 X
(16)	REAR QUARTER PANEL RH	1	1,768.30	R1 \$1,852.50 ✓
17	REAR QUARTER PANEL INNER TRIM COVERING CLIPS	12	\$6.80	NN \$81.60 X
18	REAR ALLOY RIM RH	1		Dol \$895.20 ✓
19	REAR AXLE BEAM ASSY	1		ra \$2,025.00 X
20	REAR WHEEL BEARING ASSY RH	1		NN \$402.70 X
(21)	REAR TAIL LAMP RH	1		Bra \$482.50 ✓
22	REAR TAIL LAMP PANEL RH	1		R \$338.20 X
23	REAR BUMPER <i>new</i>	1	654.30	<i>new</i> \$900.00 ✓
24	REAR BUMPER SIDE BRACKET RH	1		NN \$58.00 ✓
25	REAR FENDER INNER LINER RH	1		R \$328.60 X
26	REAR BUMPER CLIPS	8	\$5.80	NN \$46.40 X
27	REAR BUMPER LOWER LAMP RH	1		ra \$476.00 X
28	REAR BUMPER LOWER LAMP GARNISH	1		ra \$596.30 X
(29)	REAR WINDSCREEN GLASS	1		<i>Shattered</i> \$945.00 X
30	REAR WINDSCREEN RUBBER	1		NN \$120.00 X
31	REAR BOOT	1		REPAIR X
32	REAR QUARTER PANEL LOWER SILL MEMBER RH	1		REPAIR X
33	RUNNING BOARD PANEL RH	1		REPAIR X
				SUB TOTAL \$15,494.20
				LESS 20% -\$3,098.84
				PARTS TOTAL \$12,395.36
				\$9876 \$7436

Finalise:  
 Parts: \$7436  
 Net: \$90  
 Labour: \$2350  
 \$9876

→ OC 30/4/2020

Head office

6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415  
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223



Date: 09.04.2020  
 Vehicle No: SMR5354Y  
 Model: HYUNDAI AVANTE 1.6 GLS  
 Chassis: KMHD841CMLU010783-2019  
 Reg.Year: 2020

Third Party Insurer: AIG  
 Third Party Veh No: GBH371M  
 Date of Accident: 06.04.2020

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	REAR WINDSCREEN SEALANT	1		\$80.00	405a
2	REAR WINDSCREEN STOPPER	2	\$15.00	\$30.00	—
3	REAR WINDSCREEN DECAL STICKER	1		\$20.00	✓
		S/N TOTAL		\$130.00	\$90

**LABOUR CHARGES:**

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR , READJUST REAR ACCIDENT AREAS & ETC.

900/-

\$1,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT DOOR RH, REAR DOOR RH, REAR QUARTER PANEL RH, REAR BUMPER, REAR BOOT LID, RUNNING BOARD PANEL RH & ETC.

1100/-

\$1,300.00

LABOUR CHARGES TO REMOVE & REINSTALLED FRONT & REAR DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.

240.00 120/-

LABOUR CHARGES TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC.

80.00 30/-

LABOUR CHARGES TO REMOVE, REFIX, REPLACE REAR WINDSCREEN GLASS, REAR WINDSCREEN SEALANT & ETC.

120.00 ✓

LABOUR CHARGES TO REMOVE, REPLACE & READJUST REAR ABSORBER, REAR AXLE BEAM ASSY, REAR WHEEL BEARING & ETC.

350.00 X

LABOUR CHARGES TO REMOVE & REPLACE REAR ALLOY RIM RH & ETC.

80.00 20/-

TO WHEEL ALIGNMENT & BALANCING.

80.00 60/-

TO DIAGNOSE FAULTY CODE & RESET MEMORY.

120.00 X

TingAn

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

LABOUR TOTAL \$3,370.00 \$2350

TOTAL \$15,895.36

Head office

6 Kung Chong Road Singapore 159143  
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500  
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415  
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

