



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

Blk 1 Kaki Bukit Ave 6

08-04-2020

01-43

Singapore 417883

TP Budget Direct.

WOLBE6EC4HG017790

Denise.

Accident date: 18/01/2020

Estimated repair cost for vehicle no: SLN4721K OPEL ASTRA 1.4 A '17

CHASSIS: WOLBE6EC4HG017790

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>torn</i>		\$1,994.00 ✓ 1660
2	10	Front Bumper Clip <i>new</i>	\$6.50	\$65.00 30
3	2	Front Bumper Side Retainer <i>RH new</i>	\$106.00	\$212.00 106.
4	1	Front R/H Bumper Fog Lamp <i>cracked</i>		\$434.00 ✓ 295
5	1	Front R/H Bumper Fog Lamp Cover <i>lot</i>		\$105.00 ✓
6	1	Front R/H Bumper Fog Lamp Lower Cover <i>new</i>		\$69.00 X
7	1	Front R/H Headlamp <i>wt</i>		\$1,260.00 ✓
8	1	Front R/H Headlamp Lower Bracket <i>new</i>		\$79.00 X
9	1	Front R/H Fender <i>Repair</i>		\$682.00 X
10	1	Front R/H Fender Cowling <i>new</i>		\$138.00 X
11	8	Front R/H Fender Cowling Clip <i>new</i>	\$6.50	\$52.00
12	1	Front R/H Tyre <i>Not new</i>		\$380.00
13	1	Front R/H Rim <i>wt</i>		\$1,200.00 700 (SW)

3456

Subtotal :- \$6,670.00

3110-40

SW 700

Labour charges

To check wheel alignment computer

~~\$150.00~~ 80

To check wiring

~~\$100.00~~ 30

Tuff kote

810

~~\$150.00~~ x

Panel beating

~~\$800.00~~ 300

Spray painting

~~\$1,000.00~~ 400

Subtotal :- \$2,200.00

Total:- \$8,870.00

total: 462040

1/2: 3.7K.

04 Days

3.7K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: