



4/5 @ 2200

ATTN:			
NO.	DESCRIPTION - PARTS	QTY	PRICE
1	TAIL LAMP (RH) X <i>11</i>	1	\$ 927.00
2	TAIL LAMP PANEL (RH) X <i>11</i>	1	\$ 492.00
3	REAR DOOR (RH) X <i>Repair</i>	1	\$ 1016.00
4	REAR DOOR HANDLE (RH) X <i>NN</i>	1	\$ 349.00
5	REAR DOOR INNER BOARD (RH) X <i>NN</i>	1	\$ 789.00
6	REAR DOOR INNER BOARD SWITCH (RH) X <i>N N</i>	1	\$ 811.00
7	REAR DOOR LOCK (RH) X <i>N N</i>	1	\$ 412.00
8	REAR DOOR LOCK CATCH (RH) X <i>NN</i>	1	\$ 92.00
9	REAR DOOR HINGE (UPPER AND LOWER) (RH) X <i>NN</i>	2	\$ 322.00
10	REAR DOOR CHECKER (RH) X <i>NN</i>	1	\$ 181.00
11	REAR DOOR POWER WINDOW (RH) X <i>NN</i>	1	\$ 497.00
12	REAR DOOR WINDOW REGULATOR (RH) X <i>NN</i>	1	\$ 411.00
13	REAR DOOR WINDOW MOULDING (RH) X <i>NN</i>	1	\$ 135.00
14	REAR DOOR WEATHERSTRIP (RH) X <i>NN</i>	1	\$ 217.00
15	REAR DOOR INNER WEATHERSTRIP (RH) X <i>NN</i>	1	\$ 219.00
16	ROCKER PANEL (RH) X <i>NN</i>	1	\$ 1061.00
17	ROCKER PANEL GARNISH (RH) X <i>NN</i>	1	\$ 452.00
18	REAR FENDER (RH) <i>/ Ruc.</i> <i>887.20</i>	1	\$ 1819.00
19	REAR FENDER INNER TRIM (RH) X <i>NN</i>	1	\$ 341.00
20	REAR FENDER COWLING (RH) X <i>NN</i>	1	\$ 211.00
21	REAR QUARTER WINDOW MOULDING (RH) <i>/ Ruc.</i> <i>88.00</i>	1	\$ 309.00
22	REAR BUMPER <i>/ CA.</i> <i>468.20</i>	1	\$ 1061.00
23	REAR BUMPER RETAINER (RH) <i>/ Re.</i> <i>25.50</i>	1	\$ 134.00
24	REAR BUMPER BRACKET (RH) X <i>NN</i>	1	\$ 159.00
25	REAR BUMPER REINFORCEMENT BAR X <i>NN</i>	1	-
26	REAR BUMPER SPONGE X <i>NN</i>	1	-
27	REAR BUMPER REVERSE SENSOR SET X <i>NN</i>	2	\$ 294.00
28	REAR ABSORBER (RH) X <i>NN</i>	1	\$ 461.00
29	REAR BEARING HUB (RH) <i>11</i> X <i>NN</i>	1	\$ 446.00
30	REAR AXLE X <i>NN</i>	1	\$ 5146.00
31	Rear Rim set <i>R</i> X <i>(Take photos old and new)</i> <i>2186.00</i>	2	\$ 4372.00
32	Rear Tyre set X <i>NN</i>	2	\$ 1642.00
	<i>P-4521</i> SUBTOTAL	S	-
	<i>-20% - 4456.80</i> LESS 10%	S	-
	PARTS TOTAL	S	-
	SPECIAL NETT	QTY	PRICE
1	TAIL LAMP CLIPS X <i>NN</i>	2	\$ 40.00
2	REAR DOOR INNER TRIM CLIPS X <i>NN</i>	10	\$ 100.00
3	ROCKER PANEL SEALANT X <i>NN</i>	1	\$ 120.00
4	REAR FENDER SEALANT X <i>NN</i>	1	\$ 120.00

5	REAR FENDER INNER TRIM CLIPS	X ME NN	10	\$	100.00	X
6	REAR FENDER COWLING CLIPS	X NN	10	\$	100.00	X
7	REAR FENDER QUARTER WINDOW SEALANT	/ ME	1	\$	120.00	40
8	REAR BUMPER CLIPS	/ ME SN=220	10	\$	100.00	80
SPECIAL NETT TOTAL					\$ 760.00	
LABOUR			QTY	PRICE		
1	TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN		1	\$	2,400.00	600
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	680	1	\$	2,400.00	500
3	TO RUST PROOF ACCIDENT AFFECTED AREA		1	\$	250.00	60
4	TO RNR UPHOSTERY, GARNISH AND ATTACHMENT PARTS		1	\$	400.00	60
5	TO RNR DOOR MECHANISM		1	\$	400.00	X
6	TO RNR REVERSE SENSOR & CHECK FUNCTION.		1	\$	150.00	40
7	TO RNR UNDERCARRIAGE SYSTEM	11	1	\$	250.00	X 50
8	TO CHECK WHEEL ALIGNMENT		1	\$	250.00	60
9	TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION		1	\$	150.00	30
10	TO RNR TYRE AND WHEEL BALANCING		1	\$	250.00	30
11	TO DO DIAGNOSIS AND RESET, REPROGRAM OR CODING FAULT CODE.		1	\$	400.00	X
12	TO DO WATER LEAK TEST.		1	\$	80.00	X
LABOUR = \$1,610.						
TOTAL = 96,486.80					TOTAL	\$ 7,380.00
- 20% = 15,100					GRAND TOTAL COST	\$ 8,140.00

PAGE 2 OF 2

6 Days.

Imp Sum repair.

After repair photos.

Eno Riamp.

82880282

09/4/2020

LINK Auto Consultants have notified the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

9-1462.90
202
9-1170.32
S.W-90.00
2-1560.00
2820.32
20%
2256