

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHC 5995K - AIG****RIZA**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHC 5995K - RIZA**

VF1ABL15AUC281253

RENAULT

LATITUDE

23.04.2015

**AIG**

|    |   | <b>PART</b>                       |    | <b>LIST</b> |
|----|---|-----------------------------------|----|-------------|
| 1  | 1 | BUMPER COVER REAR X               | \$ | 710.55      |
| 2  | 1 | BUMPER LOWER REAR X               | \$ | 492.84      |
| 3  | 1 | BUMPER REFLECTOR LH X             | \$ | 27.96       |
| 4  | 1 | BUMEPR BRACKET SIDE LH REAR X     | \$ | 87.16       |
| 5  | 1 | BUMEPR RETAINER LH REAR X         | \$ | 28.84       |
| 6  | 1 | FENDER PANEL REAR LH X repair     | \$ | 2,114.83    |
| 7  | 1 | FENDER WHEELARCH REAR LH X repair | \$ | 348.38      |
| 8  | 1 | TAILLAMP LH X                     | \$ | 354.20      |
| 9  | 1 | ROCKER PANEL OUTER LH X repair    | \$ | 633.01      |
| 10 | 1 | DOOR PANEL REAR LH X repair       | \$ | 1,823.50    |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>6,621.27</b> |
| <b>10%</b>   | <b>\$</b> | <b>662.13</b>   |
|              | <b>\$</b> | <b>5,959.14</b> |

**Specical Nett**

|      |                                     |    |        |
|------|-------------------------------------|----|--------|
| 1SET | PARKING AID X                       | \$ | 600.00 |
| 1SET | REAR BUMPER CLIP X                  | \$ | 66.00  |
| 1SET | BUMEPR BRACKET SIDE CLIP LH RR X    | \$ | 10.00  |
| 1SET | BUMEPR RETAINER LH CLIP RR X        | \$ | 20.00  |
| 1SET | BUMPER LOWER REAR CLIP X            | \$ | 66.00  |
| 1SET | WHEELARCH CLIP REAR LH X            | \$ | 45.00  |
| 1    | DOOR STICKER "6555-3333" ✓          | \$ | 80.00  |
| 2    | Rear Windscreen Sealant X           | \$ | 80.00  |
| 1    | Rear Windscreen Inner Sponge Seal X | \$ | 150.00 |
| 1    | RIM (ROUE 7J 16H 2547) LH RR X      | \$ | 385.00 |
| 1    | TYRE LH RR X                        | \$ | 330.00 |
| 1    | CAP HUB LH REAR ✓                   | \$ | 35.60  |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>1,867.60</b> |
|--------------|-----------|-----------------|

|                    |           |                 |
|--------------------|-----------|-----------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>7,826.74</b> |
|--------------------|-----------|-----------------|

**TRANS-CAB AUTO SERVICES PTE LTD**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

**SHC 5995K - AIG****RIZA**

|                                                                                                                           |           |                                              |
|---------------------------------------------------------------------------------------------------------------------------|-----------|----------------------------------------------|
| Putty And Spray Painting Of The Affected Portion.                                                                         | \$        | <sup>540</sup><br><del>400</del><br>1,400.00 |
| Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same | \$        | <sup>400</sup><br><del>1,500.00</del>        |
| To Rust-Proofing Of The Affected Areas.                                                                                   | \$        | <del>170.00</del> 30                         |
| To reinstall rear bumper parking sensor.                                                                                  | \$        | <del>170.00</del> X                          |
| To check steering geometry and computer wheel alignment                                                                   | \$        | <del>220.00</del> X                          |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$        | <del>170.00</del> X                          |
| To transfer of rear fender fittings, attachment and perform water seepage test.                                           | \$        | <del>380.00</del> X                          |
| <b>TOTAL</b>                                                                                                              | <b>\$</b> | <b>4,010.00</b>                              |
| <b>Over All Total</b>                                                                                                     | <b>\$</b> | <b>11,836.74</b>                             |

**Repair Days****5 Days  
(PARTS BY PARTS)**

1/Calun (11/11)  
28/4/15  
After Repair photo.  
2 Repair Days.