

INS. CASE OWNER:

CC 4, AIG 1800 5807, R1 ja3 52

LKK:

IDAC:

Surveyor:

RAJUL

DOI:

ASSIGNMENT

28/03/18

Date / Time:

28/3/18

Registered in Merimen:

28/3/18

Pre-assign / CCU / FTE

EY 1292B



Insured Vehicle No.:

Name of Insured:

TAN HIAN KWEE

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

24/3/18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

DOMINIC TAN / UN KAT

Driver Tel No.:

97368494

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

2100326204

Honda Civic

AYR 7 CITY

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGV 4205B



INSRS:

WSP:

Tel:

Liability:

RMKS:

Xin Ya Auto.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

214  
809

SGV 4205B - 4/16/18 17020948/Plmb; DOA 21/03/18  
 - 28/03/18 5889/4; VOB 24/3/18  
 - 28/03/18 5889/4; VOB 26/3/18  
 EY 1292B - 04/06/18 05788/12/18; DOA 28/3/18

3UC, OI LAST B 28-1009,

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others: INS. TO WP

## PRELIMINARY ADVICE

Date/Time:

Sent By:

## FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

## FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 28

If NO or B 28, Ass. Lia :

100

Repair Cost:

S\$

-

Loss of Rental (LOR):

S\$

-

(

days)

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

-

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$250

Total:

S\$

Global Sum S\$:

## FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

-

Name 1:

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

Payee 3: (Strike if N.A.)

S\$

✓

Name 3:

12/06/19

Signature

Rogers

REF: AIG

2030+

# ASSIGNMENT

108-14194: 2022/3m

From: Date: 28/03/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SGV 4205 B

at Workshop n/s Xinya Auto

of BIK 1002 Bkt Merah Lane 3 #01-75

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 28K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS lwp

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

L/S \$5,200. x x

Veh No: SGV 4205 B Yr Regn: 2007 Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA AX10 1.5 X A C.C. 1496

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 292768 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: N2E1416034180

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/60R15

R: 2"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. 5 mm L/Bal. 5 mm

D.O.A. 24/03/18 D.O.I. 28/03/18

Survey held at XINYA

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS \$

Photos

Chairs

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Insp (\$

☐ Workshop (\$

Report Format :

Lump Sum / I.B.I. (\$



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile   |  |                             |   |
|---|--|-----------------------------|---|
| AIG ASIA PACIFIC INSURANCE PTE LTD  |  | Ref : CC4/AIG18005807/R1ja3 |   |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDING<br>SINGAPORE 079120   |  | Date : 28-03-2018           |  |
| Code : AIG  |  |                             |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |                             |   |
| Insured Veh.  | EY 1292B   | Veh. Inspected              | SGV 4205B   |
| Policy No.  |  | Coverage (\$)               | 0.00  |
| Claim No.   |  | Excess (\$)                 | 0.00  |
| Assign From   |  | Assign Date                 | 28/03/2018  |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |                             |   |
| Make & Model  |  | c.c                         | 0   |
| Engine No.  | HIDDEN   | Year of Reg.                |   |
| Chassis No.   |  | Colour                      |   |
| Odometer  | -  | Steering                    |   |
| Brakes  |  | Modification                |   |
| General   |  |                             |   |
| <b>3. Conditions of Tyres</b>   |  |                             |   |
|   | Size   | Make                        | Balance   |
| R/H Front Tyre  |  |                             | mm  |
| L/H Front Tyre  |  |                             | mm  |
| R/H Rear Tyre   |  |                             | mm  |
| L/H Rear Tyre   |  |                             | mm  |
| <b>4. Description of Damages</b>  |  |                             |   |
|   |  |                             |   |
| <b>5. General Information</b>   |  |                             |   |
| Accident Date   | 24/03/2018   | Inspection Date             | 28/03/2018  |
| Survey held at  | XINYA AUTO SERVICES PTE LTD<br>BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719 |                             |   |
| <b>5a. Remarks</b>  |  |                             |   |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                             |   |

# XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 24-Mar-18

Address : SMOOTH DR

BLK 681A JURONG WEST CENTRAL 1

# 14-96

SINGAPORE 641681

Reference : TP 1152/03/18

Vehicle No : SGV4205B

Make/Model : TOYOTA AXIO

Insurance Co. : NTUC

## RE : QUOTATION REPAIRS TO SGV 4205B FOR THIRD PARTY CLAIMS.

### PARTS REQUIRED

### QTY

### AMT \$

|     |                            |    |                                  |
|-----|----------------------------|----|----------------------------------|
| 1)  | REAR BUMPER                | 1  | \$ 1,051.20 <i>DE</i>            |
| 2)  | REAR BUMPER RETAINER       | 2  | \$ 91.20 <i>NE</i>               |
| 3)  | REAR BUMPER BRACKET        | 2  | \$ 97.20 <i>NE</i>               |
| 4)  | REAR BUMPER REVERSE SENSOR | 1  | \$ 288.01 <i>NE S/N 200</i>      |
| 5)  | TAIL LAMP                  | 2  | \$ 437.81 <i>LH-CRA L&amp;H?</i> |
| 6)  | BOOT COVER                 | 1  | \$ 539.67 <i>BT</i>              |
| 7)  | BOOT COVER WEATHERSTRIPE   | 1  | \$ 185.65 <i>NE</i>              |
| 8)  | END PANEL                  | 1  | \$ 394.60 <i>BT</i>              |
| 9)  | END PANEL GARNISH          | 1  | \$ 128.70 <i>DE</i>              |
| 10) | SPARE TYRE COVER           | 1  | \$ 168.67 <i>CUT</i>             |
| 11) | "AXIO" EMBLEM              | 1  | \$ 48.60 <i>NE</i>               |
| 12) | "TOYOTA" LOGO              | 1  | \$ 47.20 <i>NE</i>               |
| 13) | "X" LOGO                   | 1  | \$ 39.60 <i>NE</i>               |
| 14) | FRONT BUMPER               | 1  | \$ 1,154.20 <i>DE</i>            |
| 15) | FRONT BUMPER GRILLE        | 1  | \$ 285.70 <i>CRA</i>             |
| 16) | BUMPER CLIPS               | 20 | \$ 70.00 <i>NE</i>               |

LIST PRICE TOTAL

\$ 5,028.01

LESS DISCOUNT 25%

\$ 1,257.00

LIST PRICE TOTAL AFTER LESS

\$ 3,771.01

17) FRT NOS PLAE WITH CASING

\$ 55.00 *35 BT*

NETT PRICE TOTAL

\$55.00

TOTAL PARTS COST

\$3,826.01

### LABOUR AND MISCELLANEOUS CHARGES

- |                     |  |  |
|---------------------|--|--|
| 1)                  | TO REMOVE & REPLACE FRONT BUMPER & REAR COVER, REAR BUMPER AND TO PANEL BEAT CUT & WELD END PANEL INCLUDING FRT BONNET AND PANEL.          | \$ <del>1,600.00</del> <sup>1300</sup> <del>1200</del><br>(8 DAYS) |
| 2)                  | TO PUTTY AND SPRAY PAINT TO FRT AND REAR BOOT COVER, END PANEL, TYRE PANEL, BOTH REAR FENDERS, BONNET, FRT SUPPORT PANEL AND BOTH FENDERS. | \$ <del>2,400.00</del> <sup>1400</sup><br>(12 PANEL)               |
| 3)                  | TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP   | \$ <del>120.00</del> <sup>30</sup>                                 |
| 4)                  | TUFF KOTE  | \$ <del>300.00</del> <sup>150</sup>                                |
| <b>LABOUR TOTAL</b> |  | <b>\$ 4,420.00</b>   |

**TOTAL ESTIMATED REPAIR COST**

**\$ 8,246.01**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Resue  
Hp 90010068  
12 days  
4/8  
28/03/18 @ 1740  
Resy after repair

**Catherine Chong (LKK Auto)**

---

**From:** Supramaniam, Darshene <Darshene.Supramaniam@aig.com>  
**Sent:** Tuesday, 27 March, 2018 3:03 PM  
**To:** admin-a@lkkauto.com; assignments@lkkauto.com  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Chan, Yoke Shi; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Fan, Winnie-LW; Md Ishak, Mohd Imran  
**Subject:** PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE EY1292B & SGV4205B ON 24 MARCH 2018  
**Attachments:** PRE-INSPECT SGV4205B.pdf; FW: Accident involving SGV4205B & EY1292B on 24.03.18 (233 KB)

Hi,

Please refer to the enclosed request from XINYA AUTO SERVICES PTE LTD.

Claim no : 1996009934SG003  
Case Owner : Wan Nur Saliha Binte Syed Yusoff

If you have any queries/concerns, please let us know.

27032018 @ 3:10pm  
may veh in  
RCSM

Thank you.

Best Regards,

**Darshene Supramaniam**

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto  
Shared Services - Malaysia | Global Business Services

Level 12, Menara Worldwide, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia  
Tel +603 2719 6000 ext 100-2208 | Fax +603 2719 6150

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## Joy Irene (LKKAuto)

---

**From:** Syed-Yusoff, Saliha <Saliha.Syed-Yusoff@aig.com>  
**Sent:** Friday, 12 April 2019 8:50 AM  
**To:** CS A Team  
**Subject:** AIG ref: 1996009934SG-003 II TP veh : SGV4205B (DOA: 24/03/18)

**Importance:** High

Dear Team,

If there is no further correspondence from repairer, please submit w/p report.

**\*\*Do not send any further email/ reminder to repairer.**

Thank you.

Kind Regards,  
Saliha

Saliha Syed Yusoff  
AIG  
Senior Complex Claims Examiner  
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16, Singapore 079120  
Tel +(65) 6419 1917 |  
[www.aig.sg](http://www.aig.sg)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

### CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt  | Adj Submitted                                  | Ins Auth'd | Status  |
|------|---|---------------|--|--|--|------------|---|
| Main | 29 Mar 2018<br><a href="#">Edit Reg</a> |               | 27 Mar 2018<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$5,200.00</b><br><a href="#">Edit Estimates</a> | <b>S\$5,200.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

|                             |  |                        |   |
|-----------------------------|--|------------------------|---|
| Insured:                    | Tan Hian Kwee, ID: S15257973   |                        |   |
| Main Claimant:              | SMOOTH DR, Co. Reg. No.: 53322030X   |                        |   |
| Vehicle Reg. No.:           | SGV4205B   | Date of Loss:          | 24/03/2018 17:00 - :59<br>[129 Months and 10 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP / 1996009934SG  | Policy/Cover Note No.: | (Comprehensive)   |
| Vehicle Reg. No. (Insured): | EY1292B  | Policy No. (Claimant): | 5076230651-02   |
|                             |  | Excess:                |   |
| Repairer:                   | Xinya Auto Services Pte Ltd (HQ) Blk 1002, #01-75, Bukit Merah Lane 3, 159719 Bukit Merah - Tel: 6270 3481                         |                        |   |
| Handling Insurer:           | AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com |                        |   |
| Claimant's Insurer:         | NTUC Income Insurance Co-operative Ltd (HQ) - Tel:   |                        |   |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 09/04/2018]                      |                        |   |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |








































## Claim Documents

**\*SGV4205B (1996009934SG)**  
**[EY1292B]**

**TP**  
**SMOOTH DR**  
**Mar 24 2018 5:00PM**  
**[Tan Hian Kwee]**  
**Xinya Auto Services Pte Ltd**

| <a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a> |                 |                                   | <a href="#">View</a> <a href="#">View in Browser</a>   |                                     |
|---|-----------------|-----------------------------------|--|-------------------------------------|
| Photos/Images   |                 |                                   | 3 per page   | <input checked="" type="checkbox"/> |
| No  | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1   | 23/05/19 16:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 2   | 23/05/19 16:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 3   | 23/05/19 16:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 4   | 23/05/19 16:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 5   | 23/05/19 16:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 6   | 23/05/19 16:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 7   | 23/05/19 16:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 8   | 23/05/19 16:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 9   | 23/05/19 16:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 10  | 23/05/19 16:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 11  | 23/05/19 16:48  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 12  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 13  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 14  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 15  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 16  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 17  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 18  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 19  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 20  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 21  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 22  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 23  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 24  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 25  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 26  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 27  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 28  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 29  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 30  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 31  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 32  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 33  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 34  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 35  | 23/05/19 16:48  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images |                 |   | 3 per page ▼ | <input checked="" type="checkbox"/> |
|---------------|-----------------|---|--------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail    | Print                               |
| 36            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 37            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 38            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 39            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 40            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 41            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 42            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 43            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 44            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 45            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 46            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 47            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 48            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 49            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 50            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 51            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 52            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 53            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 54            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 55            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 56            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 57            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 58            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 59            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 60            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 61            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 62            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 63            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 64            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| 65            | 23/05/19 16:48  | General View                              | Load JPG     | <input checked="" type="checkbox"/> |
| Documentation |                 |   | 1 per page ▼ | <input checked="" type="checkbox"/> |
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         | Thumbnail    | Print                               |
| 1             | 28/03/18 19:13  | TP GIA REPORT                             | Load PDF     |                                     |
| 2             | 28/03/18 19:13  | EMAIL FROM AIG DD 27.03.2018              | Load PDF     |                                     |
| 3             | 28/03/18 19:13  | EMAIL PRS                                 | Load PDF     |                                     |
| 4             | 28/03/18 19:13  | NOTIFICATION FROM WORKSHOP                | Load PDF     |                                     |
| 5             | 05/04/18 01:01  | TP ESTIMATE - MARKED                      | Load PDF     |                                     |
| 6             | 23/05/19 16:47  | EMAIL                                     | Load PDF     |                                     |
| No            | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG) | Thumbnail    | Print                               |
| 1             | 29/03/18 11:08  | OI GIA Report                             | Load PDF     |                                     |

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)****Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18005807/R1JA3S2  
 Date: 23/05/2019

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle  
 No: SGV4205B

Insured Vehicle No: EY1292B

Date of Loss: 24/03/2018

Nature of Claim: TP

Claim No: 1996009934SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SGV4205B**

Make &amp; Model: TOYOTA COROLLA, 1.5 X AXIO (A)

Reg. Date: 14/06/2007 (Man. Year: 2007)

Colour: White

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 1NZC603798

Chassis No: NZE1416034180

Odometer: 292768 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195/60R15

Front Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Tyre Size:

195/60R15

Rear Left Side:

Michelin 5 mm

Rear Right Side:

Michelin 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|--|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 3,826.01        | 3,625.82        | 200.19          | 5.23         |
| Miscellaneous Items                      | 0.00            | 0.00            | 0.00            |              |
| Labour                                   | 4,420.00        | 2,880.00        | 1,540.00        | 34.84        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>8,246.01</b> | <b>6,505.82</b> | <b>1,740.19</b> | <b>21.10</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>5,200.00</b> |                 |              |
| <b>Nett Amount (S\$)</b>                 | <b>8,246.01</b> | <b>5,200.00</b> | <b>3,046.01</b> | <b>36.94</b> |

## INSPECTION

Date of Assignment: 27/03/2018

Date Inspected: 28/03/2018

Inspected At:

Xinya Auto Services Pte Ltd (HQ)  
 Blk 1002, #01-75, Bukit Merah Lane 3  
 Singapore 159719

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                 | Condition   | Repairer's  | Amount       |
|-----|-----|----------|-----------------------------|-------------|-------------|--------------|
| 1   | 1   |          | *REAR BUMPER                | Deformed    | 1,051.20 FL | *1,051.20 FL |
| 2   | 2   |          | *REAR BUMPER RETAINER       | Necessary   | 91.20 FL    | *91.20 FL    |
| 3   | 2   |          | *REAR BUMPER BRACKET        | Necessary   | 97.20 FL    | *97.20 FL    |
| 4   | 1   |          | *TAIL LAMP                  | N/s Cracked | 437.81 FL   | *218.90 FL   |
| 5   | 1   |          | *BOOT COVER                 | Bent        | 539.67 FL   | *539.67 FL   |
| 6   | 1   |          | *BOOT COVER WEATHERSTRIPE   | Necessary   | 185.65 FL   | *185.65 FL   |
| 7   | 1   |          | *END PANEL                  | Bent        | 394.60 FL   | *394.60 FL   |
| 8   | 1   |          | *END PANEL GARNISH          | Deformed    | 128.70 FL   | *128.70 FL   |
| 9   | 1   |          | *SPARE TYRE COVER           | Cut         | 168.67 FL   | *168.67 FL   |
| 10  | 1   |          | *AXIO EMBLEM                | Necessary   | 48.60 FL    | *48.60 FL    |
| 11  | 1   |          | *TOYOTA LOGO                | Necessary   | 47.20 FL    | *47.20 FL    |
| 12  | 1   |          | *X LOGO                     | Necessary   | 39.60 FL    | *39.60 FL    |
| 13  | 1   |          | *FRONT BUMPER               | Deformed    | 1,154.20 FL | *1,154.20 FL |
| 14  | 1   |          | *FRONT BUMPER GRILLE        | Cracked     | 285.70 FL   | *285.70 FL   |
| 15  | 20  |          | *BUMPER CLIPS               | Necessary   | 70.00 FL    | *70.00 FL    |
| 16  | 1   |          | *REAR BUMPER REVERSE SENSOR | Not Working | 216.01 FS   | *200.00 FS   |
| 17  | 1   |          | *FRT NOS PLATE WITH CASING  | Bent        | 55.00 FS    | *35.00 FS    |

F=Franchise part, S=SpcNett, L=ListItemDisc.

|  |                 |                 |
|--|-----------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>5,011.01</b> | <b>4,756.09</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | 1,185.00        | 1,130.27        |
| <b>Total Parts (\$\$)</b>                                  | <b>3,826.01</b> | <b>3,625.82</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars  | Lab.Type | Repairer's      | Amount          |
|--------------------------------|--|----------|-----------------|-----------------|
| <b>Labour Items</b>            |  |          |                 |                 |
| 1                              | TO REMOVE & REPLACE FRONT BUMPER & REAR COVER, REAR BUMPER AND TO PANEL BEAT CUT & WELD END PANEL INCLUDING FRT BONNET AND PANEL.          | New      | 1,600.00        | 1,300.00        |
| 2                              | TO PUTTY AND SPRAY PAINT TO FRT AND REAR BOOT COVER, END PANEL, TYRE PANEL, BOTH REAR FENDERS, BONNET, FRT SUPPORT PANEL AND BOTH FENDERS. | New      | 2,400.00        | 1,400.00        |
| 3                              | TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP.  | New      | 120.00          | 30.00           |
| 4                              | TUFF KOTE.   | New      | 300.00          | 150.00          |
| <b>Gross Labour Cost (S\$)</b> |  |          | <b>4,420.00</b> | <b>2,880.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >