

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Mar 2018 Edit Reg		12 Apr 2020 00:00 Edit Adj Rpt	S\$5,200.00 Edit Estimates	S\$5,200.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Tan Hian Kwee, ID: S1525797J		
Main Claimant:	SMOOTH DR, Co. Reg. No.: 53322030X		
Vehicle Reg. No.:	SGV4205B	Date of Loss:	24/03/2018 17:00 - :59 [129 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1996009934SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	EY1292B	Policy No. (Claimant):	5076230651-02
		Excess:	
Repairer:	Xinya Auto Services Pte Ltd (HQ) Blk 1002, #01-75, Bukit Merah Lane 3, 159719 Bukit Merah - Tel: 6270 3481		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 28/02/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (26/02/2020): [Report Send Back Alerts - SGV4205B \(TP\)](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

*SGV4205B (1996009934SG)
[EY1292B]
TP
SMOOTH DR
Mar 24 2018 5:00PM
[Tan Hian Kwee]
Xinya Auto Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			☒		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown													Edit				
Photos/Images															3 per page			☒		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)													Thumbnail		Print		
1	23/05/19 16:48		General View													Load JPG		☒		
2	23/05/19 16:48		General View													Load JPG		☒		
3	23/05/19 16:48		General View													Load JPG		☒		
4	23/05/19 16:48		General View													Load JPG		☒		
5	23/05/19 16:48		General View													Load JPG		☒		
6	23/05/19 16:48		General View													Load JPG		☒		
7	23/05/19 16:48		General View													Load JPG		☒		
8	23/05/19 16:48		General View													Load JPG		☒		
9	23/05/19 16:48		General View													Load JPG		☒		
10	23/05/19 16:48		General View													Load JPG		☒		
11	23/05/19 16:48		General View													Load JPG		☒		
12	23/05/19 16:48		General View													Load JPG		☒		
13	23/05/19 16:48		General View													Load JPG		☒		
14	23/05/19 16:48		General View													Load JPG		☒		
15	23/05/19 16:48		General View													Load JPG		☒		
16	23/05/19 16:48		General View													Load JPG		☒		
17	23/05/19 16:48		General View													Load JPG		☒		
18	23/05/19 16:48		General View													Load JPG		☒		
19	23/05/19 16:48		General View													Load JPG		☒		
20	23/05/19 16:48		General View													Load JPG		☒		
21	23/05/19 16:48		General View													Load JPG		☒		
22	23/05/19 16:48		General View													Load JPG		☒		
23	23/05/19 16:48		General View													Load JPG		☒		
24	23/05/19 16:48		General View													Load JPG		☒		
25	23/05/19 16:48		General View													Load JPG		☒		
26	23/05/19 16:48		General View													Load JPG		☒		
27	23/05/19 16:48		General View													Load JPG		☒		
28	23/05/19 16:48		General View													Load JPG		☒		
29	23/05/19 16:48		General View													Load JPG		☒		
30	23/05/19 16:48		General View													Load JPG		☒		
31	23/05/19 16:48		General View													Load JPG		☒		
32	23/05/19 16:48		General View													Load JPG		☒		

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
33	23/05/19 16:48	General View		Load JPG	☒
34	23/05/19 16:48	General View		Load JPG	☒
35	23/05/19 16:48	General View		Load JPG	☒
36	23/05/19 16:48	General View		Load JPG	☒
37	23/05/19 16:48	General View		Load JPG	☒
38	23/05/19 16:48	General View		Load JPG	☒
39	23/05/19 16:48	General View		Load JPG	☒
40	23/05/19 16:48	General View		Load JPG	☒
41	23/05/19 16:48	General View		Load JPG	☒
42	23/05/19 16:48	General View		Load JPG	☒
43	23/05/19 16:48	General View		Load JPG	☒
44	23/05/19 16:48	General View		Load JPG	☒
45	23/05/19 16:48	General View		Load JPG	☒
46	23/05/19 16:48	General View		Load JPG	☒
47	23/05/19 16:48	General View		Load JPG	☒
48	23/05/19 16:48	General View		Load JPG	☒
49	23/05/19 16:48	General View		Load JPG	☒
50	23/05/19 16:48	General View		Load JPG	☒
51	23/05/19 16:48	General View		Load JPG	☒
52	23/05/19 16:48	General View		Load JPG	☒
53	23/05/19 16:48	General View		Load JPG	☒
54	23/05/19 16:48	General View		Load JPG	☒
55	23/05/19 16:48	General View		Load JPG	☒
56	23/05/19 16:48	General View		Load JPG	☒
57	23/05/19 16:48	General View		Load JPG	☒
58	23/05/19 16:48	General View		Load JPG	☒
59	23/05/19 16:48	General View		Load JPG	☒
60	23/05/19 16:48	General View		Load JPG	☒
61	23/05/19 16:48	General View		Load JPG	☒
62	23/05/19 16:48	General View		Load JPG	☒
63	23/05/19 16:48	General View		Load JPG	☒
64	23/05/19 16:48	General View		Load JPG	☒
65	23/05/19 16:48	General View		Load JPG	☒
66	13/07/20 09:07	Reinspection Photo		Load JPG	☒
67	13/07/20 09:07	Reinspection Photo		Load JPG	☒
68	13/07/20 09:07	Reinspection Photo		Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	28/03/18 19:13	TP GIA REPORT		Load PDF	
2	28/03/18 19:13	EMAIL FROM AIG DD 27.03.2018		Load PDF	
3	28/03/18 19:13	EMAIL PRS		Load PDF	
4	28/03/18 19:13	NOTIFICATION FROM WORKSHOP		Load PDF	
5	05/04/18 01:01	TP ESTIMATE - MARKED		Load PDF	
6	23/05/19 16:47	EMAIL		Load PDF	
7	09/12/20 08:40	Correspondence Email with 3rd Party		Load PDF	
8	09/12/20 08:40	3rd Party ACRA Letter		Load PDF	
9	10/12/20 09:04	Authorisation to Act		Load PDF	
10	10/12/20 09:04	GIA SEARCH		Load PDF	
11	10/12/20 09:04	LOD		Load PDF	
12	10/12/20 09:04	Release Voucher		Load PDF	

Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
13	10/12/20 09:04	RENTAL RECEIPT		Load PDF
14	10/12/20 09:04	WORKSHOP INVOICE		Load PDF
15	10/12/20 09:16	INVOICE NO DATED 23.05.2019		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	29/03/18 11:08	OI GIA Report		Load PDF
2	24/02/20 14:54	Letter of Demand from Third Party		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	EY1292B (Insd veh)	Model:	TOYOTA COROLLA 1.5 X AXIO
	SGV4205B (TP veh)		(A)
Date of Accident:	24/03/2018		

Global Sum Settlement	:	☒ [X]	Yes	☐ []	No
Repair Estimate	:	\$			8,246.01
Final Repair Cost	:	\$			5,830.00
Loss of Use	:	\$			12.00 days at \$60.00 per day
Rental (if any)	:	\$			days
LTA / GIA Search Fee	:	\$			
Others:	:	\$			
	:	\$			
Final Settlement Sum (GLOBAL SUM)	:	\$			5,830.00

Is Third Party Workshop GIA Registered?				☐ []	YES	☒ [X]	NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u>:				Agreed Liability _____ 100 _____ (%)				
B) For <u>GIA Registered Workshop</u>:				BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)				Assessed Liability (*): _____ 100 _____ (%)				
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>								
Remarks _____								

Payment Instruction: Payee's Breakdown			
1)	Xinya Auto Services Pte Ltd	:	\$ 5,830.00
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

10 Dec
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG18005807/R1PA3S2-1**Date:** 10/12/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SGV4205B**Insured Vehicle No :** EY1292B

Date of Loss: 24/03/2018

Nature of Claim: TP Claim No: 1996009934SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGV4205B**

Make & Model: TOYOTA COROLLA, 1.5 X AXIO (A)

Engine No: 1NZC603798

Reg. Date: 14/06/2007 (Man. Year: 2007)

Chassis No: NZE1416034180

Colour: White

Odometer: 292768 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15

Rear Tyre Size: 195/60R15

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,826.01	3,625.82	200.19	5.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,420.00	2,880.00	1,540.00	34.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,246.01	6,505.82	1,740.19	21.10
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	8,246.01	5,200.00	3,046.01	36.94
+ Loss of Use (12.0 x S\$60.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,922.00		
Global Sum Settlement (S\$)		5,830.00		

INSPECTION

Date of Assignment: 12/04/2020

Date Inspected: 28/03/2018

Inspected At:

Xinya Auto Services Pte Ltd (HQ)
Blk 1002, #01-75, Bukit Merah Lane 3
Singapore 159719

Estimated Period of Repair: 12.0 days

12/10/2020

Adjuster Report

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,051.20 FL	*1,051.20 FL
2	2		*REAR BUMPER RETAINER	Necessary	91.20 FL	*91.20 FL
3	2		*REAR BUMPER BRACKET	Necessary	97.20 FL	*97.20 FL
4	1		*TAIL LAMP	N/s Cracked	437.81 FL	*218.90 FL
5	1		*BOOT COVER	Bent	539.67 FL	*539.67 FL
6	1		*BOOT COVER WEATHERSTRIPE	Necessary	185.65 FL	*185.65 FL
7	1		*END PANEL	Bent	394.60 FL	*394.60 FL
8	1		*END PANEL GARNISH	Deformed	128.70 FL	*128.70 FL
9	1		*SPARE TYRE COVER	Cut	168.67 FL	*168.67 FL
10	1		*AXIO EMBLEM	Necessary	48.60 FL	*48.60 FL
11	1		*TOYOTA LOGO	Necessary	47.20 FL	*47.20 FL
12	1		*X LOGO	Necessary	39.60 FL	*39.60 FL
13	1		*FRONT BUMPER	Deformed	1,154.20 FL	*1,154.20 FL
14	1		*FRONT BUMPER GRILLE	Cracked	285.70 FL	*285.70 FL
15	20		*BUMPER CLIPS	Necessary	70.00 FL	*70.00 FL
16	1		*REAR BUMPER REVERSE SENSOR	Not Working	216.01 FS	*200.00 FS
17	1		*FRT NOS PLATE WITH CASING	Bent	55.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,011.01	4,756.09
- List Item Discount on L Items 25.00/25.00% (S\$)	1,185.00	1,130.27
Total Parts (S\$)	3,826.01	3,625.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE FRONT BUMPER & REAR COVER, REAR BUMPER AND TO PANEL BEAT CUT & WELD END PANEL INCLUDING FRT BONNET AND PANEL.	New	1,600.00	1,300.00
2	TO PUTTY AND SPRAY PAINT TO FRT AND REAR BOOT COVER, END PANEL, TYRE PANEL, BOTH REAR FENDERS, BONNET, FRT SUPPORT PANEL AND BOTH FENDERS.	New	2,400.00	1,400.00
3	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP.	New	120.00	30.00
4	TUFF KOTE.	New	300.00	150.00
Gross Labour Cost (S\$)			4,420.00	2,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >